EurotestXE

MI 3102H BT, MI 3102 BT

Instruction manual

Version 1.0, Code no. 20 752 160

METREL®

Distributor:

Manufacturer:

METREL d.d.
Ljubljanska cesta 77
1354 Horjul
Slovenia
web site: http://www.metrel.si
e-mail: metrel@metrel.si

CE Mark on your equipment certifies that this equipment meets the requirements of the EU (European Union) concerning safety and electromagnetic compatibility regulations

© 2013 METREL

The trade names Metrel, Smartec, Eurotest, Autosequence are trademarks registered or pending in Europe and other countries.
No part of this publication may be reproduced or utilized in any form or by any means without permission in writing from METREL.

Table of contents

1 Preface 9

2 Safety and operational considerations 10

2.1 Warnings and notes 10
2.2 Battery and charging 15
2.3 Standards applied 17

3 Instrument description 19

3.1 Front panel 19
3.2 Connector panel 20
3.3 Back side 21
3.4 Carrying the instrument 22
3.4.1 Secure attachment of the strap 23
3.5 Instrument set and accessories 24
3.5.1 Standard set MI 3102H BT – EurotestXE 24
3.5.2 Standard set MI 3102 BT – EurotestXE 24
3.5.3 Optional accessories 24

4 Instrument operation 25

4.1 Display and sound 25
4.1.1 Terminal voltage monitor 25
4.1.2 Battery indication 25
4.1.3 Messages 25
4.1.4 Results 26
4.1.5 Sound warnings 26
4.1.6 Help screens 26
4.1.7 Backlight and contrast adjustments 27
4.2 Function selection 27
4.3 Instruments main menu 29
4.4 Settings 29
4.4.1 Memory 30
4.4.2 Language 30
4.4.3 Date and time 30
4.4.4 Earthing system (MI 3102 BT only) 31
4.4.5 RCD testing 31
4.4.6 Z factor 33
4.4.7 Commander support 33
4.4.8 Initial settings 34
4.4.9 Clamp Settings 36
4.4.10 Length units 37

5 Measurements 38

5.1 Voltage, frequency and phase sequence 38
5.2 Insulation resistance 40
5.3 The DAR and PI diagnostic (MI 3102H BT only) 42
5.4 Resistance of earth connection and equipotential bonding 44
5.4.1 Continuous resistance measurement 45
5.4.2 R LOWΩ, 200 mA resistance measurement 46

5.4.3 Continuous resistance measurement with low current 47
5.4.4 Compensation of test leads resistance 49
5.5 Ring continuity (only with EASI switch A 1214) 50
5.6 Testing RCDs 53
5.6.1 Contact voltage (RCD Uc) 54
5.6.2 Trip-out time (RCDt) 55
5.6.3 Trip-out current (RCD I) 55
5.6.4 RCD Autotest 57
5.7 Fault loop impedance and prospective fault current 59
5.8 Line impedance and prospective short-circuit current / Voltage drop 61
5.8.1 Line impedance and prospective short circuit current 62
5.8.2 Voltage drop 63
5.9 Earth resistance 65
5.9.1 Standard earthing resistance measurement 66
5.9.2 Contactless earthing resistance measurement (with two current clamps) 67
5.9.3 Specific earth resistance measurement 68
5.10 PE test terminal 70
5.11 Current 72
5.12 First fault leakage current – ISFL (MI 3102 BT only) 73
5.13 Testing of insulation monitoring devices – IMD (MI 3102 BT only) 75
5.14 PE conductor resistance 78
5.15 Illumination 80

6 Auto-sequences 82

7 Data handling 87

7.1 Memory organization 87
7.2 Data structure 87
7.3 Storing test results 89
7.4 Recalling test results 90
7.5 Clearing stored data 91
7.5.1 Clearing complete memory content 91
7.5.2 Clearing measurement(s) in selected location 91
7.5.3 Clearing individual measurements 92
7.5.4 Renaming installation structure elements (upload from PC) 93
7.5.5 Renaming installation structure elements with serial barcode reader or RFID reader 93
7.6 Communication 94
7.6.1 USB and RS232 communication 94
7.6.2 Bluetooth communication 94

8 Upgrading the instrument 97

9 Maintenance 98

9.1 Fuse replacement 98
9.2 Cleaning 98
9.3 Periodic calibration 98
9.4 Service 98

10 Technical specifications 99

10.1 Insulation resistance 99
10.2 Diagnostic test (MI 3102H BT only) 100

10.3 Continuity 101
10.3.1 Resistance R LOW, R2, R1+R2 101
10.3.2 Resistance CONTINUITY 101
10.3.3 RING Continuity 101
10.4 RCD testing 102
10.4.1 General data 102
10.4.2 Contact voltage RCD Uc 102
10.4.3 Trip-out time 103
10.4.4 Trip-out current 103
10.5 Fault loop impedance and prospective fault current 104
10.5.1 No disconnecting device or FUSE selected 104
10.5.2 RCD selected 104
10.6 Line impedance and prospective short-circuit current / Voltage drop 105
10.7 PE conductor resistance 106
10.7.1 No RCD selected 106
10.7.2 RCD selected 106
10.8 Resistance to earth 107
10.8.1 Standard earthing resistance measurement – 3-wire measurement 107
10.8.2 Contactless earthing resistance measurement using two current clamps 107
10.9 Specific earth resistance measurements 107
10.10 Voltage, frequency, and phase rotation 109
10.10.1 Phase rotation 109
10.10.2 Voltage 109
10.10.3 Frequency 109
10.10.4 Online terminal voltage monitor 109
10.11 TRMS Clamp current 110
10.12 First fault leakage current – ISFL (MI 3102 BT only) 111
10.13 Calibrated resistance for IMD testing (MI 3102 BT only) 111
10.14 Illumination 112
10.14.1 Illumination (Luxmeter sensor, type B) 112
10.14.2 Illumination (Luxmeter sensor, type C) 112
10.15 General data 113

Appendix A – Fuse table 114

A.1 Fuse table – impedances (UK) 114

Appendix B – Accessories for specific measurements 116

Appendix C – Commander (A 1401) 118

C.1 ⚠ Warnings related to safety 118
C.2 Battery 118
C.3 Description of commander 118
C.4 Operation of commander 119

1 Preface 6

2 Safety and operational considerations 7

2.1 Warnings and notes 7
2.2 Battery and charging 12
2.3 Standards applied 14

3 Instrument description 16

3.1 Front panel 16
3.2 Connector panel 17
3.3 Back side 18
3.4 Carrying the instrument 19
3.4.1 Secure attachment of the strap 20
3.5 Instrument set and accessories 21
3.5.1 Standard set MI 3102H BT – EurotestXE 21
3.5.2 Standard set MI 3102 BT – EurotestXE 21
3.5.3 Optional accessories 21

4 Instrument operation 22

4.1 Display and sound 22
4.1.1 Terminal voltage monitor 22
4.1.2 Battery indication 22
4.1.3 Messages 22
4.1.4 Results 23
4.1.5 Sound warnings 23
4.1.6 Help screens 23
4.1.7 Backlight and contrast adjustments 24
4.2 Function selection 24
4.3 Instruments main menu 26
4.4 Settings 26
4.4.1 Memory 27
4.4.2 Language 27
4.4.3 Date and time 27
4.4.4 Earthing system (MI 3102 BT only) 28
4.4.5 RCD testing 28
4.4.6 Z factor 30
4.4.7 Commander support 30
4.4.8 Initial settings 31
4.4.9 Clamp Settings 33
4.4.10 Length units 34

5 Measurements 35

5.1 Voltage, frequency and phase sequence 35
5.2 Insulation resistance 37
5.3 The DAR and PI diagnostic (MI 3102H BT only) 39
5.4 Resistance of earth connection and equipotential bonding 41
5.4.1 Continuous resistance measurement 42
5.4.2 R LOWΩ, 200 mA resistance measurement 43
5.4.3 Continuous resistance measurement with low current 44
5.4.4 Compensation of test leads resistance 46
5.5 Ring continuity 47
5.6 Testing RCDs 50
5.6.1 Contact voltage (RCD Uc) 51
5.6.2 Trip-out time (RCDt) 52
5.6.3 Trip-out current (RCD I) 52
5.6.4 RCD Autotest 54
5.7 Fault loop impedance and prospective fault current 56

5.8 Line impedance and prospective short-circuit current / Voltage drop 58
5.8.1 Line impedance and prospective short circuit current 59
5.8.2 Voltage drop 60
5.9 Earth resistance 62
5.9.1 Standard earthing resistance measurement 63
5.9.2 Contactless earthing resistance measurement (with two current clamps) 64
5.9.3 Specific earth resistance measurement 65
5.10 PE test terminal 67
5.11 Current 69
5.12 First fault leakage current – ISFL (MI 3102 BT only) 70
5.13 Testing of insulation monitoring devices – IMD (MI 3102 BT only) 72
5.14 PE conductor resistance 75
5.15 Illumination 77

6 Auto-sequences 79

7 Data handling 85

7.1 Memory organization 85
7.2 Data structure 85
7.3 Storing test results 87
7.4 Recalling test results 88
7.5 Clearing stored data 89
7.5.1 Clearing complete memory content 89
7.5.2 Clearing measurement(s) in selected location 89
7.5.3 Clearing individual measurements 90
7.5.4 Renaming installation structure elements (upload from PC) 91
7.5.5 Renaming installation structure elements with serial barcode reader or RFID reader 91
7.6 Communication 92
7.6.1 USB and RS232 communication 92
7.6.2 Bluetooth communication 92

8 Upgrading the instrument 94

9 Maintenance 95

9.1 Fuse replacement 95
9.2 Cleaning 95
9.3 Periodic calibration 95
9.4 Service 95

10 Technical specifications 96

10.1 Insulation resistance 96
10.2 Diagnostic test (MI 3102H BT only) 97
10.3 Continuity 98
10.3.1 Resistance R LOW 98
10.3.2 Resistance CONTINUITY 98
10.4 RCD testing 99
10.4.1 General data 99
10.4.2 Contact voltage RCD Uc 99
10.4.3 Trip-out time 100
10.4.4 Trip-out current 100
10.5 Fault loop impedance and prospective fault current 101

10.5.1 No disconnecting device or FUSE selected 101
10.5.2 RCD selected 101
10.6 Line impedance and prospective short-circuit current / Voltage drop 102
10.7 PE conductor resistance....103
10.7.1 No RCD selected....103
10.7.2 RCD selected 103
10.8 Resistance to earth 104
10.8.1 Standard earthing resistance measurement – 3-wire measurement 104
10.8.2 Contactless earthing resistance measurement using two current clamps 104
10.9 Specific earth resistance measurements....104
10.10 Voltage, frequency, and phase rotation 106
10.10.1 Phase rotation 106
10.10.2 Voltage 106
10.10.3 Frequency....106
10.10.4 Online terminal voltage monitor 106
10.11 TRMS Clamp current 107
10.12 First fault leakage current – ISFL (MI 3102 BT only) 108
10.13 Calibrated resistance for IMD testing (MI 3102 BT only)....108
10.14 Illumination....109
10.14.1 Illumination (Luxmeter sensor, type B) 109
10.14.2 Illumination (Luxmeter sensor, type C) 109
10.15 General data 110

Appendix A – Fuse table 111

A.1 Fuse table – impedances (UK) 111

Appendix B – Accessories for specific measurements 113

Appendix C – Commander (A 1401) 115

C.1 ⚠ Warnings related to safety 115
C.2 Battery 115
C.3 Description of commander....115
C.4 Operation of commander....116

1 Preface

Congratulations on your purchase of the Eurotest instrument and its accessories from METREL. The instrument was designed on a basis of rich experience, acquired through many years of dealing with electric installation test equipment.

The Eurotest instrument is a professional, multifunctional, hand-held test instrument intended to perform all the measurements on a.c. electrical LV installations.

The following measurements and tests can be performed:

- Voltage and frequency,
- Continuity tests,
- Insulation resistance tests,
- Diagnostic tests (MI 3102H BT only),
- RCD testing,
- Fault loop / RCD trip-lock impedance measurements,
- Line impedance / Voltage drop,
- Phase sequence,
- Earthing resistance tests,
- Current measurements,
- Illumination,
- First fault current (MI 3102 BT only),
- Testing of insulation monitoring devices – IMD (MI 3102 BT only) and
- Pre-defined auto-sequences.

The graphic display with backlight offers easy reading of results, indications, measurement parameters and messages. Two LED PASS/FAIL indicators are placed at the sides of the LCD.
The operation of the instrument is designed to be as simple and clear as possible and no special training (except for the reading this instruction manual) is required in order to begin using the instrument.
In order for operator to be familiar enough with performing measurements in general and their typical applications it is advisable to read METREL handbook ***Guide for testing and verification of low voltage installations***.

The instrument is equipped with the entire necessary accessory for comfortable testing.

2 Safety and operational considerations

2.1 Warnings and notes

In order to maintain the highest level of operator safety while carrying out various tests and measurements, METREL recommends keeping your Eurotest instruments in good condition and undamaged. When using the instrument, consider the following general warnings:

General warnings related to safety:

- **The ⚠ symbol on the instrument means »Read the Instruction manual with special care for safe operation«. The symbol requires an action!**
- **If the test equipment is used in a manner not specified in this user manual, the protection provided by the equipment could be impaired!**
- **Read this user manual carefully, otherwise the use of the instrument may be dangerous for the operator, the instrument or for the equipment under test!**
- **Do not use the instrument or any of the accessories if any damage is noticed!**
- **Consider all generally known precautions in order to avoid risk of electric shock while dealing with hazardous voltages!**
- **In case a fuse has blown follow the instructions in this manual in order to replace it! Use only fuses that are specified!**
- **Do not use the instrument in AC supply systems with voltages higher than 550 Va.c.**
- **Service, repairs or adjustment of instruments and accessories is only allowed to be carried out by a competent authorized personnel!**
- **Use only standard or optional test accessories supplied by your distributor!**
- **Consider that protection category of some accessories is lower than of the instrument. Test tips and Tip commander have removable caps. If they are removed the protection falls to CAT II. Check markings on accessories!**
  cap off, 18 mm tip: CAT II up to 1000 V
  cap on, 4 mm tip: CAT II 1000 V / CAT III 600 V / CAT IV 300 V
- **The instrument comes supplied with rechargeable Ni-MH battery cells. The cells should only be replaced with the same type as defined on the battery compartment label or as described in this manual. Do not use standard alkaline battery cells while the power supply adapter is connected, otherwise they may explode!**

- **Hazardous voltages exist inside the instrument. Disconnect all test leads, remove the power supply cable and switch off the instrument before removing battery compartment cover.**
- **Do not connect any voltage source on C1 input. It is intended only for connection of current clamps. Maximal input voltage is 3 V!**
- **All normal safety precautions must be taken in order to avoid risk of electric shock while working on electrical installations!**

Warnings related to safety of measurement functions:

Insulation resistance

- Insulation resistance measurement should only be performed on de-energized objects!
- Do not touch the test object during the measurement or before it is fully discharged! Risk of electric shock!
- When an insulation resistance measurement has been performed on a capacitive object, automatic discharge may not be done immediately! The warning message and the actual voltage are displayed during discharge until voltage drops below 30 V.
- Do not connect test terminals to external voltage higher than 600 V (AC or DC) in order not to damage the test instrument!

Continuity functions

- Continuity measurements should only be performed on de-energized objects!
- Parallel loops may influence on test results.

Testing PE terminal

- If phase voltage is detected on the tested PE terminal, stop all measurements immediately and ensure the cause of the fault is eliminated before proceeding with any activity!

Notes related to measurement functions:

General

- The indicator means that the selected measurement cannot be performed because of irregular conditions on input terminals.
- Insulation resistance, continuity functions and earth resistance measurements can only be performed on de-energized objects.
- PASS / FAIL indication is enabled when limit is set. Apply appropriate limit value for evaluation of measurement results.
- In the case that only two of the three wires are connected to the electrical installation under test, only voltage indication between these two wires is valid.

Insulation resistance

- The standard three-wire test lead, plug test cable or Plug / Tip commanders can be used for the insulation test with voltages ≤ 1kV.
- The special two wire 2.5 kV test lead must be used for the insulation test with 2.5 kV. (MI 3102H BT only).
- If a voltage of higher than 30 V (AC or DC) is detected between test terminals, the insulation resistance measurement will not be performed.
- The instrument automatically discharge tested object after finished measurement.
- A double click of TEST key starts a continuous measurement.

Continuity functions

- If a voltage of higher than 10 V (AC or DC) is detected between test terminals, the continuity resistance test will not be performed.
- Compensate test lead resistance before performing a continuity measurement, where necessary.

Earth resistance - RE, two clamps, specific earth resistance (ρ)

- If voltage between test terminals is higher than 30 V the resistance to earth measurement will not be performed.
- If a noise voltage higher than approx. 5 V is present between the H and E or S test terminals, "" (noise) warning symbol will be displayed, indicating that the test result may not be correct!
- For two clamps earth resistance measurement clamps A 1018 and A 1019 should be used. Clamps A 1391 are not supported.
- For specific earth resistance measurements ρ Adaptor A 1199 should be used.

RCD functions

- Parameters set in one function are also kept for other RCD functions!
- The measurement of contact voltage does not normally trip an RCD. However, the trip limit of the RCD may be exceeded as a result of leakage current flowing to the PE protective conductor or a capacitive connection between L and PE conductors.
- The RCD trip-lock sub-function (function selector in LOOP position) takes longer to complete but offers much better accuracy of fault loop resistance (in comparison to the R_L sub-result in Contact voltage function).
- RCD trip-out time and RCD trip-out current measurements will only be performed if the contact voltage in the pre-test at nominal differential current is lower than the set contact voltage limit!
- The auto-test sequence (RCD AUTO function) stops when trip-out time is out of allowable time period.

Z-LOOP

- The low limit prospective short-circuit current value depends on fuse type, fuse current rating, fuse trip-out time and impedance scaling factor.

- The specified accuracy of tested parameters is valid only if the mains voltage is stable during the measurement.
- Fault loop impedance measurements will trip an RCD.
- The measurement of fault loop impedance using trip-lock function does not normally trip an RCD. However, the trip limit may be exceeded if a leakage current flows to the PE protective conductor or if there is a capacitive connection between L and PE conductors.

Z-LINE / Voltage drop

- In case of measurement of $Z_{Line-Line}$ with the instrument test leads PE and N connected together the instrument will display a warning of dangerous PE voltage. The measurement will be performed anyway.

Current

- Select appropriate current clamp model and measuring range that are best fitted to the expected current values.
- Consider polarity of current clamp (arrow on test clamp should be oriented toward connected load), otherwise result will be negative!

Illumination

- For accurate measurement make sure that the milk glass bulb is lit without any shadows cast by hand, body or other unwanted objects.
- It is very important to know that the artificial light sources reach full power of operation after a period of time (see technical data for light sources) and should be therefore switched on for this period of time before the measurements are taken.

Testing PE terminal

- PE terminal can be tested in RCD, LOOP and LINE function selector positions only!
- For correct testing of PE terminal, the TEST key has to be touched for a few seconds.
- Make sure to stand on non-isolated floor while carrying out the test, otherwise test result may be wrong!

PE conductor resistance

- The specified accuracy of tested parameters is valid only if the mains voltage is stable during the measurement.
- PE conductor resistance measurement will trip an RCD.
- The measurement of PE conductor resistance using trip-lock function does not normally trip an RCD. However, the trip limit may be exceeded if a leakage current flows to the PE protective conductor or if there is a capacitive connection between L and PE conductors.

Testing of Insulation monitoring devices (IMD) (MI 3102 BT only)

- It is recommended to disconnect all appliances from the tested supply to receive regular test results. Any connected appliance will influence the insulation resistance threshold test.
- The displayed resistances and currents are indicative only. Displayed resistance can significantly differ from the actual resistance the Eurotest simulates. If IMD's with very low test currents (below 1mA) are checked the displayed resistance value is typically lower (and current higher) than the actual simulated resistance. The difference is lower for lower set resistances.

Auto-sequence tests

See notes related to tests / measurements of selected auto-sequence.

2.2 Battery and charging

The instrument uses six AA size alkaline or rechargeable Ni-MH battery cells. Nominal operating time is declared for cells with nominal capacity of 2100 mAh. Battery condition is always displayed in the lower right display part. In case the battery is too weak the instrument indicates this as shown in figure 2.1. This indication appears for a few seconds and then the instrument turns itself off.



Figure 2.1: Discharged battery indication

The battery is charged whenever the power supply adapter is connected to the instrument. The power supply socket polarity is shown in figure 2.2. Internal circuit controls charging and assures maximum battery lifetime.

Figure 2.2: Power supply socket polarity

Symbols:

	Indication of battery charging

Figure 2.3: Charging indication

Warnings related to safety:

- When connected to an installation, the instruments battery compartment can contain hazardous voltage inside! When replacing battery cells or before opening the battery/fuse compartment cover, disconnect any measuring accessory connected to the instrument and turn off the instrument,
- Ensure that the battery cells are inserted correctly otherwise the instrument will not operate and the batteries could be discharged.
- Do not recharge alkaline battery cells!
- Use only power supply adapter delivered from the manufacturer or distributor of the test equipment !

Notes:

- The charger in the instrument is a pack cell charger. This means that the battery cells are connected in series during the charging. The battery cells have to be equivalent (same charge condition, same type and age).
- If the instrument is not to be used for a long period of time, remove all batteries from the battery compartment.
- Alkaline or rechargeable Ni-MH batteries (size AA) can be used. METREL recommends only using rechargeable batteries with a capacity of 2100mAh or above.

- Unpredictable chemical processes can occur during the charging of battery cells that have been left unused for a longer period (more than 6 months). In this case METREL recommends to repeat the charge / discharge cycle at least 2-4 times.
- If no improvement is achieved after several charge / discharge cycles, then each battery cell should be checked (by comparing battery voltages, testing them in a cell charger, etc). It is very likely that only some of the battery cells are deteriorated. One different battery cell can cause an improper behaviour of the entire battery pack!
- The effects described above should not be confused with the normal decrease of battery capacity over time. Battery also loses some capacity when it is repeatedly charged / discharged. This information is provided in the technical specification from battery manufacturer.

2.3 Standards applied

The Eurotest instruments are manufactured and tested in accordance with the following regulations:

Electromagnetic compatibility (EMC)	
BS EN 61326	Electrical equipment for measurement, control and laboratory use – EMC requirements Class B (Hand-held equipment used in controlled EM environments)
Safety (LVD)	
BS EN 61010-1	Safety requirements for electrical equipment for measurement, control and laboratory use – Part 1: General requirements
BS EN 61010-2-030	Safety requirements for electrical equipment for measurement, control and laboratory use – Part 2-030: Particular requirements for testing and measuring circuits
BS EN 61010-031	Safety requirements for electrical equipment for measurement, control and laboratory use – Part 031: Safety requirements for hand-held probe assemblies for electrical measurement and test
BS EN 61010-2-032	Safety requirements for electrical equipment for measurement, control, and laboratory use - Part 2-032: Particular requirements for hand-held and hand-manipulated current sensors for electrical test and measurement
Functionality	
BS EN 61557	Electrical safety in low voltage distribution systems up to 1000 V_{AC} and 1500 V_{AC} – Equipment for testing, measuring or monitoring of protective measures Part 1: General requirements Part 2: Insulation resistance Part 3: Loop resistance Part 4: Resistance of earth connection and equipotential bonding Part 5: Resistance to earth Part 6: Residual current devices (RCDs) in TT and TN systems Part 7: Phase sequence Part 10: Combined measuring equipment Part 12: Performance measuring and monitoring devices (PMD)
DIN 5032	Photometry Part 7: Classification of illuminance meters and luminance meters
Reference standards for electrical installations and components	
BS EN 61008	Residual current operated circuit-breakers without integral overcurrent protection for household and similar uses
BS EN 61009	Residual current operated circuit-breakers with integral overcurrent protection for household and similar uses
IEC 60364-4-41	Electrical installations of buildings Part 4-41 Protection for safety – protection against electric shock
BS 7671	IEE Wiring Regulations (17th edition)
AS/NZS 3017	Electrical installations – Verification guidelines

Note about EN and IEC standards:

- Text of this manual contains references to European standards. All standards of EN 6XXXX (e.g. EN 61010) series are equivalent to IEC standards with the same number (e.g. IEC 61010) and differ only in amended parts required by European harmonization procedure.

3 Instrument description

3.1 Front panel



Figure 3.1: Front panel

Legend:

1	**LCD**	128 x 64 dots matrix display with backlight.	
2	**UP**	Modifies selected parameter.	
3	**DOWN**		
4	**TEST**	TEST	Starts measurements. Acts also as the PE touching electrode.
5	**ESC**	Goes one level back.	
6	**TAB**	Selects the parameters in selected function.	
7	**Backlight, Contrast**	Changes backlight level and contrast.	
8	**ON / OFF**	Switches the instrument power on or off. The instrument automatically turns off 15 minutes after the last key was pressed.	
9	**HELP / CAL**	Accesses help menus. Calibrates test leads in Continuity functions. Starts Z_{REF} measurement in Voltage drop sub-function.	
10	**Function selector - RIGHT**	Selects test / measurement function.	
11	**Function selector - LEFT**		
12	**MEM**	Stores / recalls memory of instrument. Stores clamp settings.	
13	**Green LEDs** **Red LEDs**	Indicates PASS / FAIL of result.	

3.2 Connector panel



Figure 3.2: Connector panel

Legend:

1	**Test connector**	Measuring inputs / outputs.
2	**Charger socket**	
3	**USB connector**	Communication with PC USB (1.1) port.
4	**Protection cover**	
5	**C1**	Current clamp measuring input
6	**PS/2 connector**	Communication with PC serial port Connection to optional measuring adapters Connection to barcode / RFID reader

Warnings!

- Maximum allowed voltage between any test terminal and ground is 600 V!
- Maximum allowed voltage between test terminals on test connector is 600 V!
- Maximum allowed voltage on test terminal C1 is 3 V!
- Maximum short-term voltage of external power supply adapter is 14 V!

3.3 Back side



Figure 3.3: Back panel

Legend:

1	**Battery / fuse compartment cover**
2	**Back panel information label**
3	**Fixing screws for battery / fuse compartment cover**



Figure 3.4: Battery and fuse compartment

Legend:

1	**Fuse F1**	M 315 mA / 250 V
2	**Fuses F2 and F3**	F 4 A / 500 V (breaking capacity 50 kA)
3	**Serial number label**	
4	**Battery cells**	Size AA, alkaline / rechargeable NiMH


2
1
3
Continuity
R Low (EN 61557-4)
R: 0.12 1999
Test current: min. ±200mA at 2
Open-circuit voltage: 6.5V 9.0V
Continuity 7mA
R: 0.0 1999 Test current: max. 8.5mA
Open-circuit voltage: 6.5V 8.0V
Insulation resistance (EN 61557-2)
R: 0.18M 199.9M , Un=50V 100V 250V
R: 0.12M 999M , Un= 500V , 1kV
U: 0V 1200V
Nominal voltages: 100V , 250V , 500V , 1kV
Measuring current: min. 1mA at Rn=Un 1k /V
Short-circuit current: < 3mA
Line impedance (EN 61557-3)
RL-N,L: 0.17 1999 Ipsc: 0.20A 1.4kA
Nominal voltage: 100V 440V / 15Hz 500Hz
Fault loop impedance (EN 61557-3)
RL-PE: 0.17 1999
Ipfc : 0.14A 1.4kA
Nominal voltage: 100V 264V / 15Hz 500Hz
Voltage, frequency
U: 0V 440V / f: 15Hz 500Hz
Phase rotation (EN 61557-7)
Nominal voltage: 100V 440V / 15Hz 500Hz
Results: 1.2.3 or 2.1.3
RCD (EN 61557-6)
I : 10mA, 30mA, 100mA, 300mA, 500mA, 1A
Nominal voltage: 100V 264V / 15Hz 500Hz
Contact voltage
Uc: 0.0V 100.0V
Rs: 0.00 10.00k (Rs=Uc/ I N)
Tripping time
non-delayed (time-delayed) RCDs
1: 0ms 300ms (500ms)
2: 0ms 150ms (200ms)
5: 0ms 40ms (150ms), Uc: 0.0V 100.0V
Tripping current
I : 0.2 I N 1.1 I N AC (1.5 I N A)
t : 0ms 300ms, Uc: 0.0V 100.0V
Multiplier: 0.5, 1, 2, 5
Resistance to earth (EN 61557-5)
R: 0.04 9999
Open-circuit voltage : < 45V
Short-circuit current : < 20mA
CAT III 600V
500V
METREL
Measuring and Regulation Equipment Manufacturer d.d.
Ljubljanska 77
SI - 1354 Horjul
Tel: +386 1 75 58 200
http://www.metrel.si
20124 462

Figure 3.5: Bottom

Legend:

1	**Bottom information label**
2	**Neck belt openings**
3	**Handling side covers**

3.4 Carrying the instrument

With the neck-carrying belt supplied in standard set, various possibilities of carrying the instrument are available. Operator can choose appropriate one on basis of his operation, see the following examples:

		The instrument hangs around operators neck only – quick placing and displacing.

	The instrument can be used even when placed in soft carrying bag – test cable connected to the instrument through the front aperture.

3.4.1 Secure attachment of the strap

You can choose between two methods:



Figure 3.6: First method



Figure 3.7: Alternative method

Please perform a periodical check of the attachment.

3.5 Instrument set and accessories

3.5.1 Standard set MI 3102H BT – EurotestXE

- Instrument
- Soft carrying bag
- AC / DC current clamp
- Plug test cable
- Test lead, 3 x 1.5 m
- 2.5 kV test lead, 2 x 1.5 m
- Test probe, 4 pcs
- Crocodile clip, 4 pcs
- Set of carrying straps
- RS232-PS/2 cable
- USB cable
- Set of Ni-MH battery cells
- Power supply adapter
- CD with instruction manual, and “Guide for testing and verification of low voltage installations” handbook and PC software EurolinkPRO.
- Short instruction manual
- Calibration Certificate

3.5.2 Standard set MI 3102 BT – EurotestXE

- Instrument
- Soft carrying bag
- AC / DC current clamp
- Plug test cable
- Test lead, 3 x 1.5 m
- Test probe, 4 pcs
- Crocodile clip, 4 pcs
- Set of carrying straps
- RS232-PS/2 cable
- USB cable
- Set of Ni-MH battery cells
- Power supply adapter
- CD with instruction manual, and “Guide for testing and verification of low voltage installations” handbook and PC software EurolinkPRO.
- Short instruction manual
- Calibration Certificate

3.5.3 Optional accessories

See the attached sheet for a list of optional accessories that are available on request from your distributor.

4 Instrument operation

4.1 Display and sound

4.1.1 Terminal voltage monitor

The terminal voltage monitor displays on-line the voltages on the test terminals and information about active test terminals in the a.c. installation measuring mode.

	Online voltages are displayed together with test terminal indication. All three test terminals are used for selected measurement.
	Online voltages are displayed together with test terminal indication. L and N test terminals are used for selected measurement.
	L and PE are active test terminals; N terminal should also be connected for correct input voltage condition.
	Polarity of test voltage applied to the output terminals, L and N.
	2.5 kV Insulation measurement terminal screen. (MI 3102H BT only)

4.1.2 Battery indication

The battery indication indicates the charge condition of battery and connection of external charger.

	Battery capacity indication.
	Low battery. Battery is too weak to guarantee correct result. Replace or recharge the battery cells.
	Charging in progress (if power supply adapter is connected).

4.1.3 Messages

In the message field warnings and messages are displayed.

	Measurement is running, consider displayed warnings.
	Conditions on the input terminals allow starting the measurement; consider other displayed warnings and messages.
	Conditions on the input terminals do not allow starting the measurement, consider displayed warnings and messages.
	RCD tripped-out during the measurement (in RCD functions).
	Portable RCD selected (PRCD).
	Instrument is overheated. The measurement is prohibited until the temperature decreases under the allowed limit.

	Result(s) can be stored.
	High electrical noise was detected during measurement. Results may be impaired.
	L and N are changed.
	Warning! High voltage is applied to the test terminals.
	Warning! Dangerous voltage on the PE terminal! Stop the activity immediately and eliminate the fault / connection problem before proceeding with any activity!
	Test leads resistance in Continuity measurement is not compensated.
	Test leads resistance in Continuity measurement is compensated.
	High resistance to earth of test probes. Results may be impaired.
	Too small current for declared accuracy. Results may be impaired. Check in Current Clamp Settings if sensitivity of current clamp can be increased.
	Measured signal is out of range (clipped). Results are impaired.
	Single fault condition in IT system. (MI 3102 BT only)
	Fuse F1 is broken.

4.1.4 Results

	Measurement result is inside pre-set limits (PASS).
	Measurement result is out of pre-set limits (FAIL).
	Measurement is aborted. Consider displayed warnings and messages.

4.1.5 Sound warnings

Continuous sound	**Warning!** Dangerous voltage on the PE terminal is detected.

4.1.6 Help screens

HELP	Opens help screen.

Help menus are available in all functions. The Help menu contains schematic diagrams for illustrating how to properly connect the instrument to electric installation. After selecting the measurement you want to perform, press the HELP key in order to view the associated Help menu.

Keys in help menu:

UP / DOWN	Selects next / previous help screen.
ESC / HELP / Function selector	Exits help menu.

Figure 4.1: Examples of help screens

4.1.7 Backlight and contrast adjustments

With the BACKLIGHT key backlight and contrast can be adjusted.

Click	Toggles backlight intensity level.
Keep pressed for **1 s**	Locks high intensity backlight level until power is turned off or the key is pressed again.
Keep pressed for **2 s**	Bargraph for LCD contrast adjustment is displayed.



Figure 4.2: Contrast adjustment menu

Keys for contrast adjustment:

DOWN	Reduces contrast.
UP	Increases contrast.
TEST	Accepts new contrast.
ESC	Exits without changes.

4.2 Function selection

For selecting test / measurement function within each test mode the **FUNCTION SELECTOR** keys shall be used.

Keys:

Function selector	Selects test / measurement function.
UP / DOWN	Selects sub-function in selected measurement function.
TAB	Selects the test parameter to be set or modified.
TEST	Runs selected test / measurement function.
MEM	Stores measured results / recalls stored results.
ESC	Exits back to main menu.

Keys in **test parameter** field:

UP / DOWN	Changes the selected parameter.
TAB	Selects the next measuring parameter.

Function selector	Toggles between the main functions.
MEM	Stores measured results / recalls stored results

General rule regarding enabling **parameters** for evaluation of measurement / test result:

Parameter	**OFF**	No limit values, indication: _ _ _.
	ON	**Value(s)** – results will be marked as PASS or FAIL in accordance with selected limit.

See chapter 5 ***Measurements*** for more information about the operation of the instrument test functions.

4.3 Instruments main menu

In instrument's main menu the test mode can be selected. Different instrument options can be set in the SETTINGS menu.

- **<INSTALLATION>** a.c. LV installation testing
- **<AUTO SEQUENCES>** custom configured autosequences
- **<OTHERS>** other tests / measurements
- **<SETTINGS>** Instrument settings



Figure 4.3: Main menu

Keys:

UP / DOWN	Selects appropriate option.
TEST	Enters selected option.

4.4 Settings

Different instrument options can be set in the SETTINGS menu.

Options are:

- recalling and clearing stored results,
- selection of language,
- setting the date and time,
- setting earthing system (MI 3102 BT only),
- selection of reference standard for RCD tests,
- entering Z factor,
- commander support,
- setting the instrument and Bluetooth module to initial values,
- settings for current clamps,
- settings of length units for Earth ρ.



Figure 4.4: Options in Settings menu

Keys:

UP / DOWN	Selects appropriate option.
TEST	Enters selected option.
ESC / Function selector	Exits back to main menu.

4.4.1 Memory

In this menu the stored data can be recalled or deleted. See chapter 7 **Data handling** for more information.



Figure 4.5: Memory options

Keys:

UP / DOWN	Selects option.
TEST	Enters selected option.
ESC	Exits back to settings menu.
Function selector	Exits back to main menu without changes.

4.4.2 Language

In this menu the language can be set.

Figure 4.6: Language selection

Keys:

UP / DOWN	Selects language.
TEST	Confirms selected language and exits to settings menu.
ESC	Exits back to settings menu.
Function selector	Exits back to main menu without changes.

4.4.3 Date and time

In this menu date and time can be set.



Figure 4.7: Setting date and time

Keys:

TAB	Selects the field to be changed.
UP / DOWN	Modifies selected field.
TEST	Confirms new date / time and exits.
ESC	Exits back to settings menu.
Function selector	Exits back to main menu without changes.

Note:

- If the batteries are removed for more than 1 minute the set date and time will be lost.

4.4.4 Earthing system (MI 3102 BT only)

In this menu the earthing system can be set.

Options are:
- TN/TT
- IT



Figure 4.8: Selection of earthing system

Keys:

UP / DOWN	Selects option.
TEST	Confirms selected option and exits to settings menu.
ESC	Exits back to settings menu.
Function selector	Exits back to main menu without changes.

4.4.5 RCD testing

In this menu the used standard for RCD tests can be set.



Figure 4.9: Selection of RCD test standard

Keys:

UP / DOWN	Selects standard.
TEST	Confirms selected standard.
ESC	Exits back to settings menu.
Function selector	Exits back to main menu without changes.

Maximum RCD disconnection times differ in various standards.
The trip-out times defined in individual standards are listed below.

Trip-out times according to EN 61008 / EN 61009:

	½×$I_{\Delta N}$ *)	$I_{\Delta N}$	2×$I_{\Delta N}$	5×$I_{\Delta N}$
General RCDs (non-delayed)	t_Δ > 300 ms	t_Δ < 300 ms	t_Δ < 150 ms	t_Δ < 40 ms
Selective RCDs (time-delayed)	t_Δ > 500 ms	130 ms < t_Δ < 500 ms	60 ms < t_Δ < 200 ms	50 ms < t_Δ < 150 ms

Trip-out times according to EN 60364-4-41:

	½×$I_{\Delta N}$ *)	$I_{\Delta N}$	2×$I_{\Delta N}$	5×$I_{\Delta N}$

General RCDs (non-delayed)	t_Δ > 999 ms	t_Δ < 999 ms	t_Δ < 150 ms	t_Δ < 40 ms
Selective RCDs (time-delayed)	t_Δ > 999 ms	130 ms < t_Δ < 999 ms	60 ms < t_Δ < 200 ms	50 ms < t_Δ < 150 ms

Trip-out times according to BS 7671:

	½×$I_{\Delta N}$ *)	$I_{\Delta N}$	2×$I_{\Delta N}$	5×$I_{\Delta N}$
General RCDs (non-delayed)	t_Δ > 1999 ms	t_Δ < 300 ms	t_Δ < 150 ms	t_Δ < 40 ms
Selective RCDs (time-delayed)	t_Δ > 1999 ms	130 ms < t_Δ < 500 ms	60 ms < t_Δ < 200 ms	50 ms < t_Δ < 150 ms

Trip-out times according to AS/NZS 3017**):

		½×$I_{\Delta N}$ *)	$I_{\Delta N}$	2×$I_{\Delta N}$	5×$I_{\Delta N}$	
RCD type	$I_{\Delta N}$ [mA]	t_Δ	t_Δ	t_Δ	t_Δ	Note
I	≤ 10	> 999 ms	40 ms	40 ms	40 ms	Maximum break time
II	> 10 ≤ 30		300 ms	150 ms	40 ms	
III	> 30		300 ms	150 ms	40 ms	
IV Ⓢ	> 30	> 999 ms	500 ms	200 ms	150 ms	
			130 ms	60 ms	50 ms	Minimum non-actuating time

*) Minimum test period for current of ½×$I_{\Delta N}$, RCD shall not trip-out.
**) Test current and measurement accuracy correspond to AS/NZS 3017 requirements.

Maximum test times related to selected test current for general (non-delayed) RCD

Standard	½×$I_{\Delta N}$	$I_{\Delta N}$	2×$I_{\Delta N}$	5×$I_{\Delta N}$
EN 61008 / EN 61009	300 ms	300 ms	150 ms	40 ms
EN 60364-4-41	1000 ms	1000 ms	150 ms	40 ms
BS 7671	2000 ms	300 ms	150 ms	40 ms
AS/NZS 3017 (I, II, III)	1000 ms	1000 ms	150 ms	40 ms

Maximum test times related to selected test current for selective (time-delayed) RCD

Standard	½×$I_{\Delta N}$	$I_{\Delta N}$	2×$I_{\Delta N}$	5×$I_{\Delta N}$
EN 61008 / EN 61009	500 ms	500 ms	200 ms	150 ms
EN 60364-4-41	1000 ms	1000 ms	200 ms	150 ms
BS 7671	2000 ms	500 ms	200 ms	150 ms
AS/NZS 3017 (IV)	1000 ms	1000 ms	200 ms	150 ms

Note:

- Trip-out limit times for PRCD, PRCD-K and PRCD-S are equal to General (non-delayed) RCDs.

4.4.6 Z factor

In this menu the Z factor can be set.



Figure 4.10: Selection of Z factor

Keys:

UP / DOWN	Sets Z value.
TEST	Confirms Z value.
ESC	Exits back to settings menu.
Function selectors	Exits back to main menu without changes.

The impedance limit values for different overcurrent protective devices are scaled down by a factor 0,8 or 0,75 (Z factor). This means that the fault current will still be high enough also at increased conductor temperatures and low supply voltage. This assures a safe operation of the overcurrent protection device in all conditions.

4.4.7 Commander support

The support for remote commanders can be enabled or disabled in this menu.



Figure 4.11: Selection of commander support

Keys:

UP / DOWN	Selects commander option.
TEST	Confirms selected option.
ESC	Exits back to settings menu.
Function selector	Exits back to main menu without changes.

Note:

- Commander disabled option is intended to disable the commander's remote keys. In the case of high EM interfering noise the operation of the commander can be irregular.

4.4.8 Initial settings

In this menu the instrument settings, measurement parameters and limits can be set to initial (factory) values.
Internal Bluetooth module is initialized.



Figure 4.12: Initial settings dialogue

Keys:

UP / DOWN	Selects option [YES, NO].
TEST	Restores default settings (if YES is selected).
ESC	Exits back to settings menu.
Function selector	Exits back to main menu without changes.

Warnings:
- Customized settings will be lost when this option is used!
- If the batteries are removed for more than 1 minute the custom made settings will be lost.

The default setup is listed below:

Instrument setting	**Default value**
Language	English
Contrast	As defined and stored by adjustment procedure
Earthing system*	TN/TT
Lenght units	m
Z factor	0.80
RCD standards	BS 7671
Commander	A 1314, A 1401
Internal bluetooth	Initialization of internal Bluetooth module
Clamp settings	A1391, 40 A

Test mode: Function Sub-function	Parameters / limit value
INSTALLATION:	
EARTH RE, 2 clamps	No limit
EARTH ρ	2.0 m
R ISO	L / E No limit Utest = 500 V
Low Ohm Resistance R LOWΩ, r_1, r_n, r_2, R1+R2, R2, R1+RN,	No limit

CONTINUITY	No limit, sound OFF
Rpe	No limit
Rpe(rcd)	No limit
Z - LINE VOLTAGE DROP	Fuse type: none selected ΔU: 4.0 % Z_{REF}: 0.00 Ω
Z - LOOP	Fuse type: none selected
Zs rcd	Fuse type: none selected
RCD	RCD t Nominal differential current: $I_{\Delta N}$=30 mA RCD type: AC, non-delayed Test current starting polarity: ⏦ (0°) Limit contact voltage: 50 V Current multiplier: ×1
AUTO SEQUENCES:	
AUTO TT	FUSE: None selected Z_{REF}: --- ΔU: 4.0 % RCD: 30 mA, AC, non-delayed, ⏦ (0°) Uc: 50 V
AUTO TN (rcd)	FUSE: None selected Z_{REF}: --- ΔU: 4.0 % Rpe: No limit
AUTO TN	FUSE: None selected Z_{REF}: --- ΔU: 4.0 % Rpe: No limit
AUTO IT*	FUSE: None selected Z_{REF}: --- ΔU: 4.0 % ISFL: 3.0 mA IMD: AUTO R, 35 kΩ, 2 s
OTHERS:	
SENSOR	No limit
ISFL*	No limit
IMD*	AUTO R, 30 kΩ, 2 s
DIAG. TEST**	500 V

* MI 3102 BT only
** MI 3102H BT only

Note:

- Initial settings (reset of the instrument) can be recalled also if the TAB key is pressed while the instrument is switched on.

4.4.9 Clamp Settings

In Clamp settings menu the C1 measuring input can be configured.



Figure 4.13: Configuration of current clamp measuring input

Parameters to be set:

Model	**Model of current clamp** [A1018, A1019, A1391].
Range	**Measuring range of current clamp** [20 A], [40 A, 300 A].

Selection of measuring parameters

Keys:

UP / DOWN	Selects appropriate option.
TEST	Enables changing data of selected parameter.
MEM	Saves settings.
ESC	Exits back to clamp settings menu.
Function selector	Exits back to main menu without changes.

Changing data of selected parameter

Keys:

UP / DOWN	Sets parameter.
TEST	Confirms set data.
MEM	Saves settings.
ESC	Disable changing data of selected parameter.
Function selector	Exits back to main menu without changes.

Note:

- Measuring range of the instrument must be considered. Measurement range of current clamp can be higher than of the instrument.

4.4.10 Length units

Length unit for specific earth resistance measurement can be selected in this menu.



Figure 4.14: Selection of length unit

Keys:

UP / DOWN	Selects length unit.
TEST	Confirms selected option.
ESC	Exits back to settings menu.
Function selector	Exits back to main menu without changes.

5 Measurements

5.1 Voltage, frequency and phase sequence

Voltage and frequency measurement is always active in the terminal voltage monitor. In the special ***VOLTAGE TRMS menu*** the measured voltage, frequency and information about detected three-phase connection can be stored. Measurements are based on the BS EN 61557-7 standard.

See chapter ***4.2 Function selection*** for instructions on key functionality.



Figure 5.1: Voltage in single phase system

Test parameters for voltage measurement

There are no parameters to be set.

Connections for voltage measurement



Figure 5.2: Connection of 3-wire test lead and optional adapter in three-phase system



Figure 5.3: Connection of plug test cable and 3-wire test lead in single-phase system

Voltage measurement procedure

- Select the VOLTAGE TRMS function using the function selector keys.
- **Connect** test cable to the instrument.
- **Connect** test leads to the item to be tested (see *Figure 5.2* and *Figure 5.3*).
- **Store** voltage measurement result by pressing the **MEM** key (optional).

Measurement runs immediately after selection of VOLTAGE TRMS function.

Figure 5.4: Examples of voltage measurement in three-phase system

Displayed results for single phase system:

Uln .....voltage between phase and neutral conductors
Ulpe .....voltage between phase and protective conductors
Unpe .....voltage between neutral and protective conductors
f.....frequency

Displayed results for three-phase system:

U12.....voltage between phases L1 and L2
U13.....voltage between phases L1 and L3
U23.....voltage between phases L2 and L3
1.2.3 .....vorrect connection – CW rotation sequence
3.2.1 .....invalid connection – CCW rotation sequence
f.....frequency

Displayed results for IT system (MI 3102 BT only):

U12.....voltage between phases L1 and L2
U1pe .....voltage between phase L1 and protective conductor
U2pe .....voltage between phase L2 and protective conductor
f.....frequency

5.2 Insulation resistance

The insulation resistance measurement is performed in order to ensure safety against electric shock through insulation. Typical applications are:

- insulation resistance between conductors of installation,
- insulation resistance of non-conductive rooms (walls and floors),
- insulation resistance of ground cables and
- resistance of semi-conductive (antistatic) floors.

Four insulation resistance sub-functions are available:

- ISO L/E,
- ISO L/N,
- ISO L/L and
- ISO N/E.

The insulation resistance tests are carried out in the same way regardless which sub-function is selected. However it is important to select the appropriate sub-function in order to classify the measurement to be correctly considered in verification documents (Electrical Installation Certificate, Periodic Inspection Report etc.).

See chapter ***4.2 Function selection*** for instructions on key functionality.



Figure 5.5: Insulation resistance

Test parameters for insulation resistance measurement

Test	**Sub-function** [ISO L/E, ISO L/N, ISO L/L, ISO N/E]
Uiso	**Nominal test voltage** [50 V, 100 V, 250 V, 500 V, 1000 V, 2500 V*]
Limit	**Minimum insulation resistance** [OFF, 0.01 MΩ ÷ 200 MΩ]

* Nominal test voltage 2500 V is available on MI 3102H BT only.

Test circuits for insulation resistance



Figure 5.6: Connection of 3-wire test lead and tip commander (U_N ≤ 1 kV)



Figure 5.7: Connection of 2.5 kV test lead (U_N = 2.5 kV)

Insulation resistance measuring procedure

- Select the R ISO function using the function selector keys.
- Set sub-function to ISO L/E, ISO L/N, ISO L/L, or ISO N/E using **UP / DOWN** keys.
- Set the required **test voltage**.
- Enable and set **limit** value (optional).
- **Disconnect** tested installation from mains supply (and discharge insulation as required).
- **Connect** test cable to the instrument and to the item to be tested (see *Figure 5.6 and Figure 5.7*).
  Different test cable must be used for testing with nominal test voltage U_N ≤ 1000 V and U_N = 2500 V. Also different test terminals are used.
  The standard three-wire test lead, Plug test cable or plug / tip commanders can be used for the insulation test with nominal test voltages ≤ 1000 V. For the 2500 V insulation test the two wire 2.5 kV test lead should be used.
- Press the **TEST** key to perform the measurement (double click for continuous measurement and later press to stop the measurement).
- After the measurement is finished wait until tested item is fully discharged.
- **Store** the result by pressing the **MEM** key (optional).



Figure 5.8: Example of insulation resistance measurement result

Displayed results:

R.....insulation resistance
Um .....test voltage (actual value)

5.3 The DAR and PI diagnostic (MI 3102H BT only)

Analysing the changes in the measured insulation resistance over time and calculating the **DAR** (**D**ielectric **A**bsorption **R**ation) and **PI** (**P**olarization **I**ndex) are very useful maintenance tests of an insulating materials.
Diagnostic test is a long duration test for evaluating the quality of the insulation material under test. The results of this test enable the decision to be made on the preventive replacement of the insulation material.

DAR is ratio of insulation resistance values measured after 15 seconds and after 1 minute. The DC test voltage is present during the whole period of the measurement.

$$DAR = \frac{R_{iso}(1\ min)}{R_{iso}(15\ s)}$$

PI is the ratio of insulation resistance values measured after 1 minute and after 10 minutes. The DC test voltage is present during the whole period of the measurement

$$PI = \frac{R_{iso}(10\ min)}{R_{iso}(1\ min)}$$

For additional information regarding PI and DAR diagnostic, please refer to Metrel's handbook **Modern insulation testing**.

See chapter ***4.2 Function selection*** for instructions on key functionality.



Figure 5.9: Diagnostic tests menu

Test parameter for diagnostic tests

Uiso	**Nominal test voltage** [500 V, 1000 V, 2500 V]

Diagnostic tests procedure

- Select the DIAG. TEST function from the ***OTHERS menu***.
- Set the nominal test voltage.
- **Connect** test cable to the instrument and to the item to be tested (see *Figure 5.6 and Figure 5.7*).
  Different test cable must be used for testing with nominal test voltage $U_N \leq$ 1000 V and U_N= 2500 V. Also different test terminals are used.
  The standard three-wire test lead, Plug test cable or plug / tip commanders can be used for the diagnostic test with nominal test voltages ≤ 1000 V. For the 2500 V diagnostic test the two wire 2.5 kV test lead should be used.
- Press the **TEST** key to start the measurement. Internal timer begins to increment. When internal timer reaches 1 min R60 and DAR factor are displayed and short beep is generated.
- When internal timer reaches 10 min also PI factor is displayed and measurement is completed. (Measurement can be interrupted any time by pressing the **TEST** key again.)
- After the measurement is finished wait until tested item is fully discharged.
- **Store** the result by pressing the **MEM** key (optional).



Figure 5.10: Example of PI and DAR diagnostic test results

Displayed results:

R.....insulation resistance
U.....test voltage (actual value)
R60.....resistance after 60 seconds
DAR .....dielectric absorption ratio
PI.....polarization index

Notes:

- Diagnostic tests are available only for nominal test voltages 500 V, 1000 V and 2500V.
- If any insulation resistance values ($R_{ISO(15s)}$ or $R_{ISO(1min)}$) are overranged the DAR factor is not calculated. The result field is blank: DAR : _ _ _!
- If any insulation resistance values ($R_{ISO(1min)}$ or $R_{ISO(10min)}$) are overranged the PI factor is not calculated. The result field is blank: PI :_ _ _!

5.4 Resistance of earth connection and equipotential bonding

The resistance measurement is performed in order to ensure that the protective measures against electric shock through earth connections and bondings are effective. The following continuity sub-functions are available:

- r1,
- rN,
- r2,
- R1+R2,
- R2,
- R1+RN,
- RLOWΩ and
- Continuity.

It is important to select the appropriate sub-function in order to classify the measurement to be correctly considered in verification documents (Electrical Installation Certificate, Periodic Inspection Report etc.).The r_1, r_N, r_2, R_1+R_2 and R_2 continuity tests are carried out between L and PE terminals in the same way regardless of which sub-function is selected. The R_1+R_N, RLOWΩ and Continuity tests are carried out between L and N terminals.



Figure 5.11: R2 continuity

See chapter ***4.2 Function selection*** for instructions on key functionality.



Figure 5.12: 200 mA RLOW Ω

Test parameters for resistance measurement

Test	**Resistance measurement sub-function** [r1, r2, rN, R2, R1+R2, R1+RN, RLOWΩ, CONTINUITY]
Limit	**Maximum resistance** [OFF, 0.1 Ω ÷ 20.0 Ω]

Additional test parameter for **Continuity sub-function**

	Buzzer On (sound if resistance is lower than the set limit value) or Off

Additional key:

HELP	*Click*	Calibrates test leads in Continuity functions.
	Keep pressed for 1s	Enters Help screen

5.4.1 Continuous resistance measurement

The Continuity measurement is performed with automatic polarity reversal of the test voltage according to BS EN 61557-4.

Test circuit for continuity measurement



Figure 5.13: Connections for testing the r1, rN, r2 and R1+RN sections of the wiring in ring circuits



Figure 5.14: Connections for testing the R2 and R1+R2 sections of the wiring in final circuits

Continuity measurement procedure

- Select CONTINUITY function using the function selector switch.
- Set sub-function to (r1, rN, r2, R1+R2, R2 or R1+RN) with **UP / DOWN** keys.
- Enable and set limit (optional).
- **Connect** test cable to the instrument.
- **Compensate** the test leads resistance (if necessary, see section *5.4.4 Compensation of test leads resistance*).
- **Disconnect** tested installation from mains supply.
- **Connect** the test leads to the appropriate PE wiring (see Figure 5.13 and *Figure* 5.14*:*).
- Press the **TEST** key to perform the measurement.
- After the measurement is finished **store** the result by pressing the **MEM** key (optional).



Figure 5.15: Example of continuity result

Displayed result:

R.....continuity resistance
R+ .....result at positive polarity
R- .....result at negative test polarity

5.4.2 R LOWΩ, 200 mA resistance measurement

The resistance measurement is performed with automatic polarity reversal of the test voltage.

Test circuit for R LOWΩ measurement



Figure 5.16: Connection of 3-wire test lead plus optional extension lead

R LOWΩ measurement procedure

- Select CONTINUITY function using the function selector keys.
- Set sub-function to R LOWΩ using **UP / DOWN** keys.
- Enable and set **limit** (optional).
- **Connect** test cable to the instrument.
- **Compensate** the test leads resistance if necessary, (see section *5.4.4 Compensation of test leads resistance)*.
- **Disconnect** from mains supply and discharge installation to be tested.
- **Connect** the test leads to the appropriate PE wiring (*see Figure 5.16*).
- Press the **TEST** key to perform the measurement.
- After the measurement is finished **store** the result by pressing the **MEM** key (optional).



Figure 5.17: Example of RLOW result

Displayed result:

R.....R LOWΩ resistance
R+ .....result at positive polarity
R- .....result at negative test polarity

5.4.3 Continuous resistance measurement with low current

In general, this function serves as standard Ω-meter with a low testing current. The measurement is performed continuously without polarity reversal. The function can also be applied for testing continuity of inductive components.

Test circuit for continuous resistance measurement



Figure 5.18: Tip commander and 3-wire test lead applications

Continuous resistance measurement procedure

- Select CONTINUITY function using the function selector keys.
- Set sub-function to CONTINUITY using **UP / DOWN** keys.
- Enable and set the **limit** (optional).
- **Connect** test cable to the instrument.
- **Compensate** test leads resistance if necessary, (see section *5.4.4 Compensation of test leads resistance)*.
- **Disconnect** from mains supply and discharge the object to be tested.
- **Connect** test leads to the tested object (see *Figure 5.18:*).
- Press the **TEST** key to begin performing a continuous measurement.
- Press the **TEST** key to stop measurement.
- After the measurement is finished **store** the result by pressing the **MEM** key (optional).



Figure 5.19: Example of continuous resistance measurement

Displayed result:

R.....resistance

5.4.4 Compensation of test leads resistance

This chapter describes how to compensate the test leads resistance in Continuity function. Compensation is required to eliminate the influence of test leads resistance and the internal resistances of the instrument on the measured resistance. The lead compensation is therefore very important to obtain correct result. There are two separated calibration values:

- one for r_1, r_N, r_2, R_1+R_2 and R_2,
- one for R_1+R_N, RlowΩ and Continuity.

The CAL symbol is displayed in the Continuity message fields if the compensation was carried out successfully.

Circuits for compensating the resistance of test leads

Figure 5.20: Examples of connections for compensation

Compensation of test leads resistance procedure

- Select the CONTINUITY function using the function selector keys.
- **Connect** test cable to the instrument and short the test leads together appropriately (*see Figure 5.20:*).
- Press the **CAL** key to perform test lead compensation.
- If the leads were successfully calibrated the resistance with old calibration data is displayed first and 0.00 Ω afterwards.

Figure 5.21: Results with old (left) and new (right) calibration values

Notes:

- The highest value for lead compensation is 5 Ω. If the resistance is higher the compensation value is set back to default value.
- CAL is displayed if no calibration value is stored.

5.5 Ring continuity (only with EASI switch A 1214)

With Easy Switch A1214 the resistance measurements in final ring circuits can be simplified. The Easy Switch cares for correct connectivity at the switchboard. r_1, r_2, r_N or R_1+R_N, R_1+R_2 measurements can be performed in one go.



Figure 5.22: Ring continuity r1, r2, rN

See chapter ***4.2 Function selection*** for instructions on key functionality.



Figure 5.23: Ring continuity R1+RN, R1+R2

Test parameters for ring continuity measurement

Test	**Resistance measurement sub-function** [(r1, r2, rN), (R1+RN, R1+R2)]

The ring continuity measurement is performed with automatic polarity reversal of the test voltage according to BS EN 61557-4.

Test circuit for ring continuity measurement



Figure 5.24: Step 1 – measurement of resistance r1, r2 and rN



Figure 5.25: Step 2 – measurement of resistance R1+RN and R1+R2

Ring continuity measurement procedure

Step 1: r_1, r_2, r_N resistance measuring procedure

- Select RING function using the function selector keys.
- Set sub-function to RING r1, r2, rN using **UP / DOWN** keys.
- **Connect** test cable to the instrument.
- **Compensate** the test leads resistance if necessary, (see section *5.4.4 Compensation of test leads resistance).*
- **Connect** Easy switch to the instrument (see *Figure 5.24:*).
- **Connect** Easy switch to the final ring circuit. The electrical installation must be de-energized during the test.(*Figure 5.24:*)
- Press the **TEST** key to perform the measurement of r1, r2 and rN.
- **Commit** results by pressing **TAB** key to r1, r2 and rN.
- The r1, r2 and rN results can be cleared using the **TAB** key.
- After the measurement is finished **store** the result by pressing the **MEM** key (optional).

From r_1, r_N and r_2 results reference values $(R_1+R_N)/4$, $(R_1+R_2)/4$ are calculated. The results are kept until they are changed or cleared. Take care that measuring leads are compensated.

Figure 5.26: Examples of ring continuity test – step 1

Displayed result:

r1.....ring resistance of line conductors (measured and committed)

rN.....ring resistance of neutral conductors (measured and committed)

r2.....ring resistance of protective conductors (measured and committed)

Step 2: R1+RN, R1+R2 resistance measuring procedure

- Easy switch must stay connected to the final ring circuit The electrical installation must be de-energized during the test (see *Figure 5.25:*).
- Select RING function using the function selector keys.
- Set sub-function to RING R1+RN, R1+R2 using **UP / DOWN** key.
- **Connect** plug cable or test cable to the instrument.
- **Compensate** the test leads resistance if necessary, (see chapter *5.4.4 Compensation of test leads resistance*).
- **Connect** plug cable or test cable to a socket in final ring circuit.
- Press the **TEST** key to perform the measurement.
- For correct ring wiring the results must be approximately the same as reference value (r1+rN)/4 and (r1+r2)/4. The resistance R1+R2 slightly increases with length if cross-section of PE conductor is smaller than of line conductor.
- **Commit** results by pressing **TAB** key to R1+rRN and R1+R2 positions.
- Perform measurement on the next socket in final ring circuit.
- **Commit** results by pressing **TAB** key again. The results will be committed only if they are higher as the previous results.
- The R1+RN and R1+R2 results can be cleared with the **TAB** key.
- **Repeat** the measurement on all sockets of the final ring circuit.
- After the measurement are finished **store** the result by pressing the **MEM** key (optional).

Figure 5.27: Examples of ring continuity test – step 2

Displayed results:

R1+RN ....reference test value, committed and measured
R1+R2.....reference test value, committed and measured
(r1+r2)/4..calculated reference value
(r1+rN)/4 .calculated reference value

5.6 Testing RCDs

Various test and measurements are required for verification of RCD(s) in RCD protected installations. Measurements are based on the EN 61557-6 standard.
The following measurements and tests (sub-functions) can be performed:

- contact voltage,
- trip-out time,
- trip-out current and
- RCD autotest.

See chapter ***4.2 Function selection*** for instructions on key functionality.



Figure 5.28: RCD tests

Test parameters for RCD test and measurement

TEST	**RCD sub-function test** [Uc, RCDt, RCD I, AUTO]
$I_{\Delta N}$	**Rated RCD residual current sensitivity $I_{\Delta N}$** [10 mA, 30 mA, 100 mA, 300 mA, 500 mA, 1000 mA].
type	**RCD type** [AC, A, F, B*, B+*]. **starting polarity** [0°, 90°, 180°, 270°, ⊕*, ⊖*]. **Characteristic and PRCD selection** [selective S, general non-delayed □, PRCD, PRCD-K, PRCD-S].
MUL	**Multiplication factor for test current** [½, 1, 2, 5 $I_{\Delta N}$].
Ulim	**Conventional touch voltage limit** [25 V, 50 V].

* Model MI 3102 BT only

Notes:

- Ulim can be selected in the Uc sub-function only.
- Selective (time-delayed) RCDs have delayed response characteristics. As the contact voltage pre-test or other RCD tests influence the time delayed RCD it takes a certain period to recover into normal state. Therefore a time delay of 30 s is inserted before performing trip-out test by default.
- Portable RCDs (PRCD, PRCD-K and PRCD-S) are tested as general (non-delayed) RCDs. Trip-out times, trip-out currents and contact voltage limits are equal to limits of general (non-delayed) RCDs.

Connections for testing RCD



Figure 5.29: Connecting the plug test cable and the 3-wire test lead

5.6.1 Contact voltage (RCD Uc)

A current flowing into the PE terminal causes a voltage drop on earth resistance, i.e. voltage difference between PE equipotential bonding circuit and earth. This voltage difference is called contact voltage and is present on all accessible conductive parts connected to the PE. It shall always be lower than the conventional safety limit voltage. The contact voltage is measured with a test current lower than ½ $I_{\Delta N}$ to avoid trip-out of the RCD and then normalized to the rated $I_{\Delta N}$.

Contact voltage measurement procedure

- Select the RCD function using the function selector keys.
- Set sub-function to Uc using **UP / DOWN** keys.
- Set test **parameters** (if necessary).
- **Connect** test cable to the instrument.
- **Connect** test leads to the item to be tested (see *Figure 5.29*).
- Press the **TEST** key to perform the measurement.
- **Store** the result by pressing the **MEM** key (optional).

The contact voltage result relates to the rated nominal residual current of the RCD and is multiplied by an appropriate factor (depending on RCD type and type of test current). The 1.05 factor is applied to avoid negative tolerance of result. See *Table 5.1* for detailed contact voltage calculation factors.

RCD type		Contact voltage Uc proportional to	Rated $I_{\Delta N}$	Notes
AC	⎍	$1.05 \times I_{\Delta N}$	any	All models
AC	Ⓢ	$2 \times 1.05 \times I_{\Delta N}$		
A, F	⎍	$1.4 \times 1.05 \times I_{\Delta N}$	≥ 30 mA	
A, F	Ⓢ	$2 \times 1.4 \times 1.05 \times I_{\Delta N}$		
A, F	⎍	$2 \times 1.05 \times I_{\Delta N}$	< 30 mA	
A, F	Ⓢ	$2 \times 2 \times 1.05 \times I_{\Delta N}$		
B, B+	⎍	$2 \times 1.05 \times I_{\Delta N}$	any	Model MI 3102BT only
B, B+	Ⓢ	$2 \times 2 \times 1.05 \times I_{\Delta N}$		

Table 5.1: Relationship between Uc and $I_{\Delta N}$

Loop resistance is indicative and calculated from Uc result (without additional proportional factors) according to: $R_L = \frac{U_C}{I_{\Delta N}}$.



Figure 5.30: Example of contact voltage measurement results

Displayed results:

Uc..... contact voltage
Rl..... fault loop resistance
Rmax ..... Maximum earth fault loop resistance value according to BS 7671

5.6.2 Trip-out time (RCDt)

Trip-out time measurement verifies the sensitivity of the RCD at different residual currents.

Trip-out time measurement procedure

- Select the RCD function using the function selector keys.
- Set sub-function to RCDt using **UP / DOWN** keys.
- Set test **parameters** (if necessary).
- **Connect** test cable to the instrument.
- **Connect** test leads to the item to be tested (see *Figure 5.29*).
- Press the **TEST** key to perform the measurement.
- **Store** the result by pressing the **MEM** key (optional).



Figure 5.31: Example of trip-out time measurement results

Displayed results:

t.....trip-out time
Uc.....contact voltage for rated $I_{\Delta N}$

5.6.3 Trip-out current (RCD I)

A continuously rising residual current is intended for testing the threshold sensitivity for RCD trip-out. The instrument increases the test current in small steps through appropriate range as follows:

RCD type	Slope range		Waveform	Notes
	Start value	End value		

AC	$0.2\times I_{\Delta N}$	$1.1\times I_{\Delta N}$	Sine	All models
A, F ($I_{\Delta N} \geq$ 30 mA)	$0.2\times I_{\Delta N}$	$1.5\times I_{\Delta N}$	Pulsed	
A, F ($I_{\Delta N}$ = 10 mA)	$0.2\times I_{\Delta N}$	$2.2\times I_{\Delta N}$		
B, B+	$0.2\times I_{\Delta N}$	$2.2\times I_{\Delta N}$	DC	Model MI 3102BT only

Maximum test current is I_{Δ} (trip-out current) or end value in case the RCD didn't trip-out.

Trip-out current measurement procedure

- Select the RCD function using the function selector keys.
- Set sub-function to RCD I using **UP / DOWN** keys.
- Set test **parameters** (if necessary).
- **Connect** test cable to the instrument.
- **Connect** test leads to the item to be tested (see *Figure 5.29*).
- Press the **TEST** key to perform the measurement.
- **Store** the result by pressing the **MEM** key (optional).



Figure 5.32: Trip-out current measurement result example

Displayed results:

I.....trip-out current
Uci.....contact voltage at trip-out current I or end value in case the RCD didn't trip
t.....trip-out time

5.6.4 RCD Autotest

RCD autotest function is intended to perform a complete RCD test (trip-out time at different residual currents, trip-out current and contact voltage) in one set of automatic tests, guided by the instrument.

Additional key:

HELP	*Click*	Toggles between top and bottom part of results field.
	Keep pressed for 1s	Enters Help screen

RCD autotest procedure

RCD Autotest steps	**Notes**
❑ Select the RCD function using the function selector keys. ❑ Set sub-function to AUTO using **UP / DOWN** keys. ❑ Set test **parameters** (if necessary). ❑ **Connect** test cable to the instrument. ❑ **Connect** test leads to the item to be tested (see *Figure 5.29*). ❑ Press the **TEST** key to perform the test.	Start of test
❑ Test with $I_{\Delta N}$, 0° (step 1).	RCD should trip-out
❑ **Re-activate RCD**. ❑ Test with $I_{\Delta N}$, 180° (step 2).	RCD should trip-out
❑ **Re-activate RCD**. ❑ Test with $5\times I_{\Delta N}$, 0° (step 3).	RCD should trip-out
❑ **Re-activate RCD**. ❑ Test with $5\times I_{\Delta N}$, 180° (step 4).	RCD should trip-out
❑ **Re-activate RCD**. ❑ Test with $½\times I_{\Delta N}$, 0° (step 5). ❑ Test with $½\times I_{\Delta N}$, 180° (step 6).	RCD should not trip-out RCD should not trip-out
❑ Trip-out current test, 0° (step 7).	RCD should trip-out
❑ **Re-activate RCD**. ❑ Trip-out current test, 180° (step 8).	RCD should trip-out
❑ **Re-activate RCD**. ❑ **Store** the result by pressing the **MEM** key (optional).	End of test

Result examples:



Step 1



Step 2



Step 3 *Step 4*

Step 5 *Step 6*

Step 7 *Step 8*

Figure 5.33: Individual steps in RCD autotest

Top *Bottom*

Figure 5.34: Two parts of result field in RCD autotest

Displayed results:

x1 .....step 1 trip-out time (I_Δ=$I_{\Delta N}$, 0º)
x1 .....step 2 trip-out time (I_Δ=$I_{\Delta N}$, 180º)
x5 .....step 3 trip-out time (I_Δ=5×$I_{\Delta N}$, 0º)
x5 .....step 4 trip-out time (I_Δ=5×$I_{\Delta N}$, 180º)
x½ .....step 5 trip-out time (I_Δ=½×$I_{\Delta N}$, 0º)
x½ .....step 6 trip-out time (I_Δ=½×$I_{\Delta N}$, 180º)
I∠.....step 7 trip-out current (0º)
I∠.....step 8 trip-out current (180º)
Uc.....contact voltage for rated $I_{\Delta N}$

Notes:

- The autotest sequence is immediately stopped if any incorrect condition is detected, e.g. excessive Uc or trip-out time out of bounds.
- Auto test is finished without x5 tests in case of testing the RCD types A and F with rated residual currents of $I_{\Delta N}$ = 300 mA, 500 mA, and 1000 mA. In this case auto test result passes if all other results pass, and indications for x5 are omitted.
- Tests for sensitivity (I∠,, steps 7 and 8) are omitted for selective type RCD.
- Trip out time measurement for B and B+ type RCDs in AUTO function is made with sine-wave test current, while trip-out current measurement is made with DC test current. (MI 3102 BT only)

5.7 Fault loop impedance and prospective fault current

Fault loop is a loop comprised by mains source, line wiring and PE path to the mains source. The instrument measures the impedance of the loop and calculates the short circuit current. The measurement is covered by requirements of the BS EN 61557-3 standard.

See chapter ***4.2 Function selection*** for instructions on key functionality.



Figure 5.35: Fault loop impedance

Test parameters for fault loop impedance measurement

Test	Selection of **fault loop impedance sub-function** [Zloop, Zs rcd]
Fuse type	Selection of **fuse type** [---, BS88-2, BS3036, BS88-3, BS1362, B, C, D]
Fuse I	**Rated current** of selected fuse
Fuse T	**Maximum breaking time** of selected fuse
Lim	**High limit fault loop impedance value** for selected fuse.

See Appendix A for reference fuse data.

Circuits for measurement of fault loop impedance



Figure 5.36: Connection of plug test cable and 3-wire test lead

Fault loop impedance measurement procedure

- Select the ZLOOP function using the function selector keys.
- Set sub-function to Zloop or Zs rcd using the **UP / DOWN** keys.
- Select test **parameters** (optional).
- **Connect** test cable to the instrument.
- **Connect** test leads to the item to be tested (see *Figure 5.29* and *Figure 5.36*).
- Press the **TEST** key to perform the measurement.
- **Store** the result by pressing the **MEM** key (optional).

Figure 5.37: Examples of loop impedance measurement result

Displayed results:

Z.....fault loop impedance
Isc.....prospective fault current,
Lim.....high limit fault loop impedance value.I

Prospective fault current I_{PFC} is calculated from measured impedance as follows:

$$I_{PFC} = \frac{U_N}{Z_{L-PE} \cdot scaling\_factor}$$

where:
Un..... Nominal $U_{L\text{-}PE}$ voltage (see table below),
Scaling factor.....Impedance correction factor (*see chapter 4.4.6*).

U_n	Input voltage range (L-PE)
110 V	(93 V ≤ $U_{L\text{-}PE}$ ≤ 134 V)
230 V	(185 V ≤ $U_{L\text{-}PE}$ ≤ 266 V)

Notes:

- High fluctuations of mains voltage can influence the measurement results (the noise sign is displayed in the message field). In this case it is recommended to repeat few measurements to check if the readings are stable.
- This measurement will trip-out the RCD in RCD-protected electrical installation if test Zloop is selected.
- Select Zs rcd measurement to prevent trip-out of RCD in RCD protected installation.

5.8 Line impedance and prospective short-circuit current / Voltage drop

Line impedance is measured in loop comprising of mains voltage source and line wiring. Line impedance is covered by the requirements of the BS EN 61557-3 standard.
The Voltage drop sub-function is intended to check that a voltage in the installation stays above acceptable levels if the highest current is flowing in the circuit. The highest current is defined as the nominal current of the circuit's fuse. The limit values are described in the standard EN 60364-5-52.

Sub-functions:

- Z LINE - Line impedance measurement according to BS EN 61557-3 and
- ΔU – Voltage drop measurement.

See chapter ***4.2 Function selection*** for instructions on key functionality.



Figure 5.38: Line impedance



Figure 5.39: Voltage drop

Test parameters for line impedance measurement

Test	Selection of **line impedance** [Zline] or **voltage drop** [ΔU] **sub-function**
FUSE type	Selection of **fuse type** [---, BS88-2, BS3036, BS88-3, BS1362, B, C, D]
FUSE I	**Rated current** of selected fuse
FUSE T	**Maximum breaking time** of selected fuse
Lim	**High limit line impedance value** for selected fuse.

See Appendix A for reference fuse data.

Additional test parameters for voltage drop measurement

ΔU_{MAX}	**Maximum voltage drop** [3.0 % ÷ 9.0 %].

Additional key:

HELP / CAL	*Click*	Measures Zref value for ΔU function.
	Keep pressed for 1s	Enters Help screen.

5.8.1 Line impedance and prospective short circuit current

Circuits for measurement of line impedance



Figure 5.40: Phase-neutral or phase-phase line impedance measurement – connection of plug test cable and 3-wire test lead

Line impedance measurement procedure

- Select the Z LINE function using the function selector keys.
- Set sub-function to Zline using **UP / DOWN** keys.
- Select test **parameters** (optional).
- **Connect** test cable to the instrument.
- **Connect** test leads to the item to be tested (see *Figure 5.40*).
- Press the **TEST** key to perform the measurement.
- **Store** the result by pressing the **MEM** key (optional).

Figure 5.41: Examples of line impedance measurement result

Displayed results:

Z.....line impedance
Isc.....prospective short-circuit current
Lim.....high limit line impedance value.

Prospective fault current I_{PFC} is calculated from measured impedance as follows:

$$I_{PFC} = \frac{U_N}{Z_{L-N(L)} \cdot scaling\_factor}$$

where:
Un..... Nominal U_{L-N} or U_{L1-L2} voltage (see table below),
Scalling factor..... Impedance correction factor (see chapter *4.4.6*).

U_n	Input voltage range (L-N or L1-L2)
110 V	(93 V ≤ U_{L-N} < 134 V)
230 V	(185 V ≤ U_{L-N} ≤ 266 V)
400 V	(321 V < U_{L-L} ≤ 485 V)

Note:

- High fluctuations of mains voltage can influence the measurement results (the noise sign is displayed in the message field). In this case it is recommended to repeat few measurements to check if the readings are stable.

5.8.2 Voltage drop

The voltage drop is calculated based on the difference of line impedance at connection points (sockets) and the line impedance at the reference point (usually the impedance at the switchboard).

Circuits for measurement of voltage drop



Figure 5.42: Phase-neutral or phase-phase voltage drop measurement – connection of plug test cable and 3-wire test lead

Voltage drop measurement procedure

Step 1: Measuring the impedance Zref at origin

- Select the Z LINE function using the function selector keys.
- Set sub-function to ΔU using **UP / DOWN** keys.
- Select test **parameters** (optional).
- **Connect** test cable to the instrument.
- **Connect** the test leads to the origin of electrical installation (see *Figure 5.42*).
- Press the **CAL** key to perform the measurement.

Step 2: Measuring the voltage drop

- Set sub-function to ΔU using **UP / DOWN** keys.
- Select test **parameters** (Fuse type must be selected).
- **Connect** test cable to the instrument.
- **Connect** the test leads to the tested points (see *Figure 5.42*).
- Press the **TEST** key to perform the measurement.

- **Store** the result by pressing the **MEM** key (optional).





Step 1 - Zref *Step 2 - Voltage drop*

Figure 5.43: Examples of voltage drop measurement result

Displayed results:

ΔU .....voltage drop
Isc .....prospective short-circuit current
Z.....line impedance at measured point
Zref .....reference impedance

Voltage drop is calculated as follows:

$$\Delta U[\%] = \frac{(Z - Z_{REF}) \cdot I_N}{U_N} \cdot 100$$

where:
ΔU.....calculated voltage drop
Z .....impedance at test point
Z_{REF}.....impedance at reference point
I_N.....rated current of selected fuse
U_N .....nominal voltage (see table below)

U_n	Input voltage range (L-N or L1-L2)
110 V	(93 V ≤ U_{L-N} < 134 V)
230 V	(185 V ≤ U_{L-N} ≤ 266 V)
400 V	(321 V < U_{L-L} ≤ 485 V)

Notes:

- If the reference impedance is not set the value of Z_{REF} is considered as 0.00 Ω.
- The Z_{REF} is cleared (set to 0.00 Ω) if pressing CAL key while instrument is not connected to a voltage source.
- I_{SC} is calculated as described in chapter 5.8.1 Line impedance and prospective short circuit current.
- If the measured voltage is outside the ranges described in the table above the ΔU result will not be calculated.
- High fluctuations of mains voltage can influence the measurement results (the noise sign is displayed in the message field). In this case it is recommended to repeat few measurements to check if the readings are stable.

5.9 Earth resistance

Earth resistance is one of the most important parameters for protection against electric shock. Main earthing arrangements, lightning systems, local earthings, soil resistivity etc can be verified with the earthing resistance test. The measurement conforms to the BS EN 61557-5 standard.

The Earth resistance main function is divided into three subfunctions:

- 3-wire earth resistance test RE for standard earth resistance tests with two earthing rods.
- Contactless earth resistance test with two current clamps (also recommended in IEC 60364-6 for urban areas), for measuring resistance to earth of individual earthing rods.
- Specific earth resistance.

See chapter ***4.2 Function selection*** for instructions on key functionality.



Figure 5.44: Earth resistance

Test parameters for earth resistance measurement

Test	**Test configuration** [EARTH RE, two clamps, ρ]
Limit	**Maximum resistance** [OFF, 1 Ω ÷ 5 kΩ]
Distance	In ρ sub-function only: **Distance between probes** [0.1 m ÷ 30.0 m] or [1 ft ÷ 100 ft]

Earth resistance measurements, common measurement procedure

- Select EARTH function using the function selector keys.
- Set sub-function to EARTH RE or EARTH 2 CLAMPS using **UP / DOWN** keys.
- Enable and set **limit** value (optional).
- **Connect** test leads to the instrument.
- **Connect** the item to be tested (see *Figure 5.45, Figure 5.46 and Figure 5.48*).
- Press the **TEST** key to perform the measurement.
- **Store** the result by pressing the **MEM** key (optional).

5.9.1 Standard earthing resistance measurement

Connections for earth resistance measurement



Figure 5.45: Resistance to earth, measurement of main installation earthing



Figure 5.46: Resistance to earth, measurement of a lighting protection system



Figure 5.47: Example of earth resistance measurement result

Displayed results for earth resistance measurement:

R.....earth resistance
Rp .....resistance of S (potential) probe
Rc.....resistance of H (current) probe

Notes:

- High resistance of S and H probes could influence the measurement results. In this case, “Rp” and “Rc” warnings are displayed. There is no PASS / FAIL indication in this case.
- High noise currents and voltages in earth could influence the measurement results. The tester displays the warning in this case.
- Probes must be placed at sufficient distance from the measured object.

5.9.2 Contactless earthing resistance measurement (with two current clamps)

The measurement enables simple testing of individual earthing rods in large earthing system. It is especially suitable for use in urban areas because there is usually no possibility to place the test probes.

Connection for contactless earthing resistance measurement



Figure 5.48: Contactless earthing resistance measurement



Figure 5.49: Example of contactless earthing resistance measurement result

Displayed results for contactless earthing resistance measurement:

R.....earthing resistance

Notes:

- For two clamps earth resistance measurement clamps A 1018 and A 1019 should be used. Clamps A 1391 are not supported.
- The distance between clamps should be at least 30 cm.
- High noise currents and voltages in earth could influence the measurement results. The tester displays the “noise” warning in this case.
- The measurement results are very accurate for resistances below 10 Ω. At higher values (several 10 Ω) the test current drops to few mA. The measuring

accuracy for small currents and immunity against noise currents must be considered! The tester displays the “low current” warning in this case.

5.9.3 Specific earth resistance measurement

The specific earth resistance (soil resistivity) is measured to determine the characteristic of the soil. The results are used to properly dimension earthing systems (size, depth, number and position of earthing rods).

Circuit for specific earth resistance measurement



Figure 5.50: Specific earth resistance measurement

Specific earth resistance measurement procedure:

- Select EARTH function using the function selector keys.
- Set sub-function to EARTH ρ using **UP / DOWN** keys.
- Select the **distance** (a) between test probes.
- **Connect** A 1199 ρ adapter to the instrument.
- **Connect** the test leads to earth probes (see *Figure 5.50*).
- Press the **TEST** key to perform the measurement.
- **Store** the result by pressing the **MEM** key (optional).



Figure 5.51: Example of specific earth resistance measurement result

Displayed results for earth resistance measurement:

ρ .....specific earth resistance
Rc.....resistance of H, E (current) probe
Rp .....resistance of S, ES (potential) probe

Notes:

- High resistance of S, H, ES, E probes could influence the measurement results. In this case, “Rp” and “Rc” warnings are displayed.
- High noise currents and voltages in earthing could influence the measurement results. The tester displays the “noise” warning in this case.

5.10 PE test terminal

It can happen that a dangerous voltage is applied to the PE wire or other accessible metal parts. This is a very dangerous situation since the PE wire and MPEs are considered to be earthed. An often reason for this fault is incorrect wiring (see examples below).
When touching the **TEST** key in all functions that requires mains supply the user automatically performs this test.

Examples for application of PE test terminal



Figure 5.52: Reversed L and PE conductors (tip commander)



Figure 5.53: Reversed L and PE conductors (application of 3-wire test lead)

PE terminal test procedure

- **Connect** test cable to the instrument.
- **Connect** test leads to the item to be tested (see *Figure 5.52* and *Figure 5.53*).
- **Touch** PE test probe (the **TEST** key) for at least one second.
- If PE terminal is connected to phase voltage the warning message is displayed, instrument buzzer is activated, and further measurements are disabled in Zloop and RCD functions.

Warning:

- If dangerous voltage is detected on the tested PE terminal, immediately stop all measurements, find and remove the fault!

Notes:

- PE test terminal is active in the INSTALLATION operating mode (except in the VOLTAGE, Low ohm, Earth and Insulation functions).
- PE test terminal does not operate in case the operator's body is completely insulated from floor or walls!
- For operation of PE test terminal on commanders refer to chapter – *Commander*.

5.11 Current

This function is intended for measurement of load and leakage currents with current clamps. One measuring input is available.

See chapter ***4.2 Function selection*** for instructions on key functionality.



Figure 5.54: Current menu

Connection for current measurement



Figure 5.55: Leakage and load current measurements

Current measurement procedure

- Select CURRENT function from the ***OTHERS menu***.
- **Connect** current clamp to the instrument.
- **Connect** the clamp to the item to be tested (see *Figure 5.55*).
- Press the **TEST** key to start the continuous measurement.
- Press the **TEST** key again to stop the measurement.
- **Store** the result by pressing the **MEM** key (optional).

Figure 5.56: Examples of current measurement result

Displayed results for current measurement:

I .....Current

Note:

- For setup of current clamps (see chapter 4.4.9 Clamp Settings).

5.12 First fault leakage current – ISFL (MI 3102 BT only)

First fault leakage current measurement is performed in order to verify the maximum current that could leak into PE from observed line. This current flows through the insulation resistance and reactance (capacitance) between the other lines and PE when the first fault is applied as short circuit between observed line and PE.

See chapter ***4.2 Function selection*** for instructions on key functionality.



Figure 5.57: ISFL measurement

Test parameters for first fault leakage current measurement

Limit	**Maximum leakage current** [OFF, 3.0 mA ÷ 19.5 mA]

Test circuit for first fault leakage current



Figure 5.58: Measurement of highest first fault leakage current with 3-wire test lead



Figure 5.59: Measurement of first fault leakage current for RCD protected circuit with 3-wire test lead

First fault leakage current measuring procedure

- Select the **ISFL** function from the ***OTHERS menu***.
- Enable and set **limit** value (optional).
- **Connect** 3-wire test lead or mains measuring cable to the instrument and tested installation (see Figure 5.58 and Figure 5.59).
- Press the **TEST** key to start measurement.
- **Store** the result by pressing the **MEM** key (optional).

Figure 5.60: Examples of measurement results for the first fault leakage current

Displayed results:

Isc1 .....first fault leakage current at single fault between L1/PE
Isc2 .....first fault leakage current at single fault between L2/PE

5.13 Testing of insulation monitoring devices – IMD (MI 3102 BT only)

This function is intended for checking the alarm threshold of insulation monitor devices (IMD) by applying a changeable resistance between L1/PE and L2/PE terminals.

See chapter ***4.2 Function selection*** for instructions on key functionality.



Figure 5.61: IMD test

Test parameters for IMD test

Type	**Test selection** [MANUAL R, MANUAL I, AUTO R, AUTO I]
Limit	**MANUAL R: Minimum insulation resistance** [OFF, 5 kΩ ÷ 640 kΩ] **MANUAL I: Maximum current** [OFF, 0.1 mA ÷ 19.9 mA] **AUTO R: Minimum insulation resistance** [OFF, 5 kΩ ÷ 640 kΩ], **Timer** [1 s ÷ 99 s] **AUTO I: Maximum current** [OFF, 0.1 mA ÷ 19.9 mA], **Timer** [1 s ÷ 99 s]

Test circuit for IMD test



Figure 5.62: Connection with 3-wire test lead

IMD test procedure (MANUAL R, MANUAL I)

- Select the **IMD** function from the **OTHERS menu**.
- Select MANUAL R or MANUAL I sub-function.
- Enable and set **limit** value.
- **Connect** 3-wire test lead to the instrument and tested item (see *Figure 5.62*).
- Press the **TEST** key for measurement.
- Press the **UP / DOWN** keys to change insulation resistance*) until IMD alarms an insulation failure for L1.
- Press the **TEST** key to change line terminal selection to L2.
- In case, when IMD switch off voltage supply, instruments automatically change line terminal selection to L2 and proceed with the test when instrument detects supply voltage.
- Press the **UP / DOWN** keys to change insulation resistance*) until IMD alarms an insulation failure for L2.
- Press the **TEST** key.
- If IMD switch off voltage supply, instrument automatically proceed to the PASS / FAIL indication.
- Use the **TAB** key to select PASS / FAIL indication.
- Press the **TEST** key to confirm selection and stop the measurement.
- **Store** the result (optional).

IMD test procedure (AUTO R, AUTO I)

- Select the **IMD** function.
- Select AUTO R or AUTO I sub-function.
- Enable and set **limit** values.
- **Connect** 3-wire test lead to the instrument and tested item (see *Figure 5.62*).
- Press the **TEST** key for measurement.
- Insulation resistance between L1-PE is decreased automatically according to limit value*) every time interval selected with timer. To speed up the test press the **UP / DOWN** keys until IMD alarms an insulation failure for L1.
- Press the **TEST** key to change line terminal selection to L2.
- In case, when IMD switch off voltage supply, instruments automatically change line terminal selection to L2 and proceed with the test when instrument detects supply voltage.
- Insulation resistance between L2-PE is decreased automatically according to limit value*) every time interval selected with timer. To speed up the test press the **UP / DOWN** keys until IMD alarms an insulation failure for L2.
- Press the TEST key.
- If IMD switch off voltage supply, instrument automatically proceed to the PASS/FAIL indication.
- Use the **TAB** key to select PASS / FAIL indication.
- Press the **TEST** key to confirm selection and stop the measurement.
- **Store** the result (optional).

*) When MANUAL R or AUTO R sub-function is selected, start value of insulation resistance is determined by $R_{start} \cong 1.5 \times R_{\lim it}$

When MANUAL I or AUTO I sub-function is selected, start value of insulation resistance is determined by $R_{start} \cong 1.5 \times \frac{U_{L1-L2}}{I_{\lim it}}$

Figure 5.63: Examples of IMD test results

Displayed results:

R1.....threshold indicative insulation resistance for L1
R2.....threshold indicative insulation resistance for L2
I1 .....calculated first fault leakage current for R1
I2 .....calculated first fault leakage current for R2

Calculated first fault leakage current at threshold insulation resistance is given as:

$$I_{1(2)} = \frac{U_{L1-L2}}{R_{1(2)}}$$

$U_{L1\text{-}L2}$ is line-line voltage. The calculated first fault current is the maximum current that would flow when insulation resistance decreases to the same value as the applied test resistance, and a first fault is assumed between opposite line and PE.

5.14 PE conductor resistance

In TN system instrument measures the resistance of the protection conductor from the power transformer to the measurement site.
In TT system the resistance of protection conductor from mains outlet to earth electrode and back to the power transformer via soil and the transformers earthing system is measured.

See chapter ***4.2 Function selection*** for instructions on key functionality.



Figure 5.64: PE conductor resistance

Test parameters for PE conductor resistance measurement

Test	**Selection of PE conductor resistance sub-function** [Rpe, Rpe(rcd)]
Lim	**Maximum resistance** [OFF, 0.1 Ω ÷ 20.0 Ω].

Circuits for measurement of PE conductor resistance



Figure 5.65: Connection of plug test cable and 3-wire test lead

PE conductor resistance measurement procedure

- Select the Rpe or Rpe(rcd) sub-function using the function selector keys and **UP** / **DOWN** keys.
- Select test **parameters** (optional).
- **Connect** test cable to the instrument.
- **Connect** test leads to the item to be tested (see *Figure 5.65*).
- Press the **TEST** key to perform the measurement.
- **Store** the result by pressing the **MEM** key (optional).

Figure 5.66: Examples of PE conductor resistance measurement result

Displayed results:

R.....PE conductor resistance

Notes:

- High fluctuations of mains voltage can influence the measurement results (the noise sign is displayed in the message field). In this case it is recommended to repeat few measurements to check if the readings are stable.
- This measurement will trip-out the RCD in RCD-protected electrical installation if test Rpe is selected.
- Select Rpe(rcd) measurement to prevent trip-out of RCD in RCD protected installation.

5.15 Illumination

The illumination measurements should be performed whenever planning or installing indoor or outdoor lighting.
Illumination measurement can be performed using LUXmeter probe connected to the PS/2 connector of the instrument. The Eurotest instrument supports LUXmeter type B and LUXmeter type C probes.

See chapter ***4.2 Function selection*** for instructions on key functionality.



Figure 5.67: Illumination

Test parameters for illumination measurement

Lim	**Manimum illumination** [OFF, 0.1 lux ÷ 20 klux].

Probe positioning for measurement of illumination



Figure 5.68: LUXmeter probe positioning

Illumination measurement procedure

- Select the SENSOR function from **OTHERS menu**.
- Select test **parameters** (optional).
- **Connect** illumination sensor to the instrument.
- Take the position of LUXmeter (see *Figure 5.68*). Make sure that LUXmeter is turned on.
- Press the **TEST** key to start the continuous measurement.
- Press the **TEST** key again to stop the measurement.
- **Store** the result by pressing the **MEM** key (optional).



Figure 5.69: Example of illumination measurement result

Displayed results:

E.....Illumination

Notes:

- For accurate measurement make sure that the milk glass bulb is lit without any shadows cast by hand, body or other unwanted objects.
- It is very important to know that the artificial light sources reach full power of operation after a period of time (see technical data for light sources) and should be therefore switched on for this period of time before the measurements are taken.

6 Auto-sequences

Auto-sequences are intended to perform automatic executing of pre-defined measurement sequences. Sequences are divided into four groups, each for selected supply system:

- AUTO TT,
- AUTO TN (RCD),
- AUTO TN and
- AUTO IT (MI 3102 BT only).

The selected sequence is carried out in one set of automatic tests, guided by the instrument.

See chapter ***4.2 Function selection*** for instructions on key functionality.



Figure 6.1: Main autosequence menu

Keys in main autosequence menu

UP / DOWN	Selects autosequence.
TEST	Enters selected autotest sequence.
ESC	Exits back to previous menu.



Figure 6.2: Auto-sequence menus



Figure 6.3: Editing parameters menus

Keys in auto-sequence and editing parameters menu

Key	Auto-sequence menu	Editing parameters menu
TAB	Enters viewing/editing test parameters.	Selects the test parameter to be set or modified.
UP / DOWN		Sets or modifies test parameters.
TEST	Runs selected autosequence.	Runs selected autosequence.
HELP / CAL *Click*	Switch between screens.	Measuring reference line impedance (when ZREF is selected).
HELP / CAL *Keep pressed for 1 s*	Enters help screens.	Enters help screens.
MEM	Stores autotest results.	
ESC	Exits back to previous menu.	Exits back to previous menu with saving changes.

The following tests / measurements can be performed for selected autosequence. Parameters in each autosequence are user-defined as follows.

Auto-sequence	Test / measurement	Available editable parameters	
AUTO TT	VOLTAGE Z LINE ΔU* Zs rcd Uc	FUSE ZREF ΔU RCD	fuse type, rated current, maximal braking time, high limit impedance value reference line impedance voltage drop limit value nominal current, RCD type, maximal contact voltage
AUTO TN (RCD)	VOLTAGE Z LINE ΔU* Zs rcd Rpe(rcd)	FUSE ZREF ΔU RPE	fuse type, rated current, maximal braking time, high limit impedance value reference line impedance voltage drop limit value maximal PE line resistance
AUTO TN	VOLTAGE Z LINE ΔU* Z LOOP Rpe	FUSE ZREF ΔU RPE	fuse type, rated current, maximal braking time, high limit impedance value reference line impedance voltage drop limit value maximal PE line resistance
AUTO IT	VOLTAGE Z LINE ΔU* ISFL IMD	FUSE ZREF ΔU ISFL IMD	fuse type, rated current, maximal braking time, high limit impedance value reference line impedance voltage drop limit value maximal leakage current test type, minimal insulation or maximal leakage current

* applicable only if Z_{REF} is set

Circuit for automatic measurement



Figure 6.4: Auto-sequence setup

Automatic measurement procedure

- Enter AUTO SEQUENCES mode from main menu.
- Select autosequence AUTO TT, AUTO TN (rcd), AUTO TN, or AUTO IT.
- Select test **parameters**.
- **Connect** test cable to the instrument.
- **Connect** the test leads to the origin of electrical installation (see *Figure 6.4 – step 1*)(optional).
- Press the **CAL** key to perform the Z_{REF} measurement (optional).
- **Connect** test leads to the item to be tested (see *Figure 6.4 – step 2*).
- Press the **TEST** key to start the auto-sequence.
- **Store** the result by pressing the **MEM** key (optional).



Step 1 *Step 2* *Step 3*

Figure 6.5: Individual steps of AUTO TT auto-sequence



Figure 6.6: Example of AUTO TT auto-sequence results

Displayed results during auto-sequence and saved results

Voltage

Displayed results for single phase system:

Uln .....voltage between phase and neutral conductors
Ulpe .....voltage between phase and protective conductors
Unpe .....voltage between neutral and protective conductors
f.....frequency

Displayed results for IT system:

U12.....voltage between phases L1 and L2
U1pe .....voltage between phase L1 and protective conductor
U2pe .....voltage between phases L2 and protective conductor
f.....frequency

Line impedance

Z.....line impedance
Isc .....prospective short-circuit current
Lim.....high limit line impedance value.

Loop impedance (Zs or Zs_{RCD})

Z.....loop impedance
Isc .....prospective fault current
Lim.....high limit fault loop impedance value.

PE conductor resistance (Rpe or Rpe_{RCD})

R.....PE conductor resistance

First fault leakage current - ISFL (AUTO IT sequence only)

Isc1 .....first fault leakage current at single fault between L1/PE
Isc2 .....first fault leakage current at single fault between L2/PE

Testing of insulation monitoring devices - IMD (AUTO IT sequence only)

R1.....threshold indicative insulation resistance for phase 1
I1 .....first fault leakage current at single fault between L1/PE
R2.....threshold indicative insulation resistance for phase 2
I2 .....first fault leakage current at single fault between L2/PE

Displayed results once auto-sequence finished and recalled results:



Figure 6.7: Example of recalled AUTO TN auto-sequence results

Function	Results field	
	Left value on display	**Right value on display**
U	**Voltage**	
	Voltage between phase and neutral. Voltage between phases L1 and L2 (IT system)	
Zln	**Line impedance**	
	Line impedance	Prospective short-circuit current
ΔU*	**Voltage drop**	
	Voltage drop (if available)	
Zs	**Loop impedance**	
	Loop impedance	Contact voltage (AUTO TT only) or Prospective fault current (AUTO TT excepted)
Zlp	**Loop impedance**	
	Loop impedance	Prospective fault current
Rpe	**PE conductor resistance**	
	PE conductor resistance	
Is	**First fault leakage current**	
	First fault leakage current at single fault between L1/PE	First fault leakage current at single fault between L2/PE
Im	**Testing of insulation monitoring devices**	
	Threshold indicative insulation resistance for phase 1	Threshold indicative insulation resistance for phase 2

Notes:

- Before starting the auto-sequence, all settings of parameters should be checked.
- ΔU measurement in each auto-sequence is enabled only if Z_{REF} is set.

7 Data handling

7.1 Memory organization

Measurement results together with all relevant parameters can be stored in the instrument's memory. After the measurement is completed, results can be stored to the flash memory of the instrument, together with the sub-results and function parameters.

7.2 Data structure

The instrument's memory place is divided into 4 levels each containing 199 locations. The number of measurements that can be stored into one location is not limited.

The data structure field describes the location of the measurement (which object, block, fuse and connection) and where can be accessed.
In the measurement field there is information about type and number of measurements that belong to the selected structure element (object and block and fuse and connection).
The main advantages of this system are:

- Test results can be organized and grouped in a structured manner that reflects the structure of typical electrical installations.
- Customized names of data structure elements can be uploaded from EurolinkPRO PCSW.
- Simple browsing through structure and results.
- Test reports can be created with no or little modifications after downloading results to a PC.



Figure 7.1: Data structure and measurement fields

Data structure field

RECALL RESULTS	Memory operation menu
[OBJ]OBJECT 001 [BLO]BLOCK 002 [FUS]FUSE 003 [CON]CONNECTION 004	Data structure field
[OBJ]OBJECT 001	**1st level:** **OBJECT:** Default location name (object and its successive number). **001:** No. of selected element.
[BLO]BLOCK 002	**2nd level:** **BLOCK:** Default location name (block and its successive number). **002:** No. of selected element.
[FUS]FUSE 003	**3rd level:**

	FUSE: Default location name (fuse and its successive number). **003:** No. of selected element.
[CON]CONNECTION 004	**4th level:** **CONNECTION:** Default location name (connection and its successive number). **004:** No. of selected element.
No.: 20 [132]	No. of measurements in selected location [No. of measurements in selected location and its sub-locations]

Measurement field

VOLTAGE TRMS	Type of stored measurement in the selected location.
No.: 1/36	No. of selected test result / No. of all stored test results in selected location.

7.3 Storing test results

After the completion of a test the results and parameters are ready for storing (icon is displayed in the information field). By pressing the **MEM** key, the user can store the results.

Figure 7.2: Save test menu

FREE:96.3%	Memory available for storing results.

Keys in save test menu - data structure field

TAB	Selects the location element (Object / Block / Fuse / Connection)
UP / DOWN	Selects number of selected location element (1 to 199)
MEM	Saves test results to the selected location and returns to the measuring function.
ESC / TEST / Function selector	Exits back to measuring function without saving.

Notes:

- The instrument offers to store the result to the last selected location by default.
- If the measurement is to be stored to the same location as the previous one just press the MEM key twice.

7.4 Recalling test results

Press the **MEM key** in a main function menu when there is no result available for storing or select MEMORY in the SETTINGS menu.



Figure 7.3: Recall menu - installation structure field selected



Figure 7.4: Recall menu - measurements field selected

Keys in recall memory menu (installation structure field selected):

TAB	Selects the location element (Object / Block / Fuse / Connection).
UP / DOWN	Selects number of selected location element (1 to 199).
Function selector / ESC	Exits back to main function menu.
TEST / MEM	Enters measurements field.

Keys in recall memory menu (measurements field selected):

UP / DOWN	Selects the stored measurement.
TAB / ESC	Returns to installation structure field.
Function selector	Exits back to main function menu.
TEST / MEM	View selected measurement results.



Figure 7.5: Example of recalled measurement result

Keys in recall memory menu (measurement results are displayed)

UP / DOWN	Displays measurement results stored in selected location.
MEM / ESC	Returns to measurements field.
TEST	Returns to installation structure field.
Function selector	Exits back to main function menu.

7.5 Clearing stored data

7.5.1 Clearing complete memory content

Select **CLEAR ALL MEMORY** in **MEMORY menu**. A warning will be displayed.



Figure 7.6: Clear all memory

Keys in clear all memory menu

TEST	Confirms clearing of complete memory content (YES must be selected with **UP / DOWN** keys).
ESC	Exits back to memory menu without changes.
Function selector	Exits back to main function menu without changes.



Figure 7.7: Clearing memory in progress

7.5.2 Clearing measurement(s) in selected location

Select **DELETE RESULTS** in **MEMORY menu**.

Figure 7.8: Clear measurements menu (data structure field selected)

Keys in delete results menu (installation structure field selected):

TAB	Selects the location element (Object / Block / Fuse / Connection).
UP / DOWN	Selects number of selected location element (1 to 199)
Function selector	Exits back to main function menu.
ESC	Exits back to memory menu.
TEST	Enters dialog box for deleting all measurements in selected location and its sub-locations.

Keys in dialog for confirmation to clear results in selected location:

TEST	Deletes all results in selected location.

MEM / ESC	Exits back to delete results menu without changes.
Function selector	Exits back to main function menu without changes.

7.5.3 Clearing individual measurements

Select **DELETE RESULTS** in **MEMORY menu**.



Figure 7.9: Menu for clearing individual measurement (installation structure field selected)

Keys in delete results menu (installation structure field selected):

TAB	Selects the location element (Object / Block / Fuse / Connection).
UP / DOWN	Selects number of selected location element (1 to 199)
Function selector	Exits back to main function menu.
ESC	Exits back to memory menu.
MEM	Enters measurements field for deleting individual measurements.

Keys in delete results menu (measurements field selected):

UP / DOWN	Selects measurement.
TEST	Opens dialog box for confirmation to clear selected measurement.
TAB / ESC	Returns to installation structure field.
Function selector	Exits back to main function menu without changes.

Keys in dialog for confirmation to clear selected result(s):

TEST	Deletes selected measurement result.
MEM / TAB / ESC	Exits back to measurements field without changes.
Function selector	Exits back to main function menu without changes.



Figure 7.10: Dialog for confirmation



Figure 7.11: Display after measurement was cleared

7.5.4 Renaming installation structure elements (upload from PC)

Default installation structure elements are »Object«, »Block«, »Fuse« and »Connection«.
In the PCSW package Eurolink-PRO default names can be changed with customized names that corresponds the installation under test. Refer to PCSW Eurolink-PRO HELP for information how to upload customized installation names to the instrument.



Figure 7.12: Example of menu with customized installation structure names

7.5.5 Renaming installation structure elements with serial barcode reader or RFID reader

Default installation structure elements are »Object«, »Block«, »Fuse« and »Connection«.
When the instrument is in the SAVE RESULTS menu location ID can be scanned from a barcode label with the barcode reader or can be read from a RFID tag with the RFID reader.



Figure 7.13: Connection of the barcode reader and RFID reader

How to change the name of memory location

- Connect the barcode reader or RFID reader to the instrument.
- In Save menu select memory location to be renamed.
- A new location name (scanned from a barcode label or a RFID tag) will be accepted by the instrument. A successful receive of the barcode or RFID tag is confirmed by two short confirmation beeps.

Note:

- Use only barcode readers and RFID readers delivered by METREL or authorized distributor.

7.6 Communication

Stored results can be transferred to a PC. A special communication program on the PC automatically identifies the instrument and enables data transfer between the instrument and the PC.
There are three communication interfaces available on the instrument: USB, RS 232 and Bluetooth.

7.6.1 USB and RS232 communication

The instrument automatically selects the communication mode according to detected interface. USB interface has priority.



Figure 7.14: Interface connection for data transfer over PC COM port

How to establish an USB or RS-232 link:

- RS-232 communication: connect a PC COM port to the instrument PS/2 connector using the PS/2 - RS232 serial communication cable;
- USB communication: connect a PC USB port to the instrument USB connector using the USB interface cable.
- Switch on the PC and the instrument.
- Run the EurolinkPRO program.
- The PC and the instrument will automatically recognize each other.
- The instrument is prepared to communicate with the PC.

The program EurolinkPRO is a PC software running on Windows XP, Windows Vista, Windows 7, and Windows 8. Read the file README_EuroLink.txt on CD for instructions about installing and running the program.

Note:

- USB drivers should be installed on PC before using the USB interface. Refer to USB installation instructions available on installation CD.

7.6.2 Bluetooth communication

The internal Bluetooth module enables easy communication via Bluetooth with PC and Android devices.

How to configure a Bluetooth link between instrument and PC

- Switch On the instrument.
- On PC configure a Standard Serial Port to enable communication over Bluetooth link between instrument and PC. Usually no code for pairing the devices is needed.
- Run the *EurolinkPRO* program*.*
- The PC and the instrument will automatically recognize each other.
- The instrument is prepared to communicate with the PC.

How to configure a Bluetooth link between instrument and Android device

- Switch On the instrument.
- Some Android applications automatically carry out the setup of a Bluetooth connection. It is preferred to use this option if it exists.
  This option is supported by Metrel's Android applications.
- If this option is not supported by the selected Android application then configure a Bluetooth link via Android device's Bluetooth configuration tool. Usually no code for pairing the devices is needed.
- The instrument and Android device are ready to communicate.

Notes:

- Sometimes there will be a demand from the PC or Android device to enter the code. Enter code 'NNNN' to correctly configure the Bluetooth link.
- The name of correctly configured Bluetooth device must consist of the instrument type plus serial number, eg. *MI 3102BT-12240429I*. If the Bluetooth module got another name, the configuration must be repeated.
- In case of serious troubles with the Bluetooth communication it is possible to reinitialize the internal Bluetooth module. The initialization is carried out during the Initial settings procedure. In case of a successful initialization "INTERNAL BLUETOOTH SEARCHING OK!" is displayed at the end of the procedure. See chapter *4.4.8*

Initial settings.

8 Upgrading the instrument

The instrument can be upgraded from a PC via the RS232 communication port. This enables to keep the instrument up to date even if the standards or regulations change. The upgrade can be carried with a help of special upgrading software and the communication cable as shown on *Figure 7.14*. Please contact your dealer for more information.

9 Maintenance

Unauthorized persons are not allowed to open the Eurotest instrument. There are no user replaceable components inside the instrument, except the battery and fuses under rear cover.

9.1 Fuse replacement

There are three fuses under back cover of the Eurotest instrument.

- **F1**
  M 0.315 A / 250 V, 20×5 mm
  This fuse protects internal circuitry for continuity functions if test probes are connected to the mains supply voltage by mistake during measurement.

- **F2, F3**
  F 4 A / 500 V, 32×6.3 mm (breaking capacity: 50 kA)
  General input protection fuses of test terminals L/L1 and N/L2.

Position of fuses can be seen in *Figure 3.4: Battery and fuse compartment* in chapter *3.3 Back side*.

Warnings:
- Disconnect all measuring accessory and switch off the instrument before opening battery / fuse compartment cover, hazardous voltage inside!
- Replace blown fuse with original type only, otherwise the instrument or accessory may be damaged and/or operator's safety impaired!

9.2 Cleaning

No special maintenance is required for the housing. To clean the surface of the instrument or accessory use a soft cloth slightly moistened with soapy water or alcohol. Then leave the instrument or accessory to dry totally before use.

Warnings:
- Do not use liquids based on petrol or hydrocarbons!
- Do not spill cleaning liquid over the instrument!

9.3 Periodic calibration

It is essential that the test instrument is regularly calibrated in order that the technical specification listed in this manual is guaranteed. We recommend an annual calibration. Only an authorized technical person can do the calibration. Please contact your dealer for further information.

9.4 Service

For repairs under warranty, or at any other time, please contact your distributor.

10 Technical specifications

10.1 Insulation resistance

Insulation resistance (nominal voltages 50 V_{DC}, 100 V_{DC} and 250 V_{DC})
Measuring range according to EN 61557 is 0.15 MΩ ÷ 199.9 MΩ.

Measuring range (MΩ)	Resolution (MΩ)	Accuracy
0.00 ÷ 19.99	0.01	±(5 % of reading + 3 digits)
20.0 ÷ 99.9	0.1	±(10 % of reading)
100.0 ÷ 199.9		±(20 % of reading)

Insulation resistance (nominal voltages 500 V_{DC} and 1000 V_{DC})
Measuring range according to EN 61557 is 0.15 MΩ ÷ 1 GΩ.

Measuring range (MΩ)	Resolution (MΩ)	Accuracy
0.00 ÷ 19.99	0.01	±(5 % of reading + 3 digits)
20.0 ÷ 199.9	0.1	±(5 % of reading)
200 ÷ 999	1	±(10 % of reading)

Insulation resistance (nominal voltage 2500V_{DC}, MI 3102H BT only)
Measuring range according to EN 61557 is 0.15 MΩ ÷ 199.9 GΩ.

Measuring range (Ω)	Resolution	Accuracy
0.00 MΩ ÷ 19.99 MΩ	0.01 MΩ	±(5 % of reading + 3 digits)
20.0 MΩ ÷ 199.9 MΩ	0.1 MΩ	±(5 % of reading)
200 MΩ ÷ 999 MΩ	1 MΩ	±(10 % of reading)
1.00 GΩ ÷ 19.99 GΩ	0.01 GΩ	±(10 % of reading)
20.0 GΩ ÷ 199.9 GΩ	0.1 GΩ	±(10 % of reading)

Voltage

Measuring range (V)	Resolution (V)	Accuracy
0 ÷ 3000	1	±(3 % of reading + 3 digits)

Nominal voltages .....50 V_{DC}, 100 V_{DC}, 250 V_{DC}, 500 V_{DC}, 1000 V_{DC}, 2500 V_{DC} (MI 3102H BT only)
Open circuit voltage .....-0 % / +20 % of nominal voltage
Measuring current.....min. 1 mA at $R_N=U_N\times1$ kΩ/V
Short circuit current..... max. 3 mA
The number of possible tests..... > 1200, with a fully charged battery
Auto discharge after test.
Specified accuracy is valid if 3-wire test lead is used while it is valid up to 100 MΩ if tip commander is used.
Specified accuracy is valid up to 100 MΩ if relative humidity > 85 %.
In case the instrument gets moistened, the results could be impaired. In such case, it is recommended to dry the instrument and accessories for at least 24 hours.
The error in operating conditions could be at most the error for reference conditions (specified in the manual for each function) ±5 % of measured value.

10.2 Diagnostic test (MI 3102H BT only)

Dielectric absorption ratio DAR*

Measuring range	Resolution	Accuracy
0.01 ÷ 9.99	0.01	±(5% of reading + 2 digits)
10.0 ÷ 100.0	0.1	±(5% of reading)

* Only for test voltages 500 V_{DC}, 1000 V_{DC} and 2500V_{DC}. If any insulation resistance values (*R_{ISO}(15s) or R_{ISO}(60s)) are overranged the* **DAR** factor is not calculated. The result field is blank: DAR:_____!

Polarization index PI**

Measuring range	Resolution	Accuracy
0.01 ÷ 9.99	0.01	±(5% of reading + 2 digits)
10.0 ÷ 100.0	0.1	±(5% of reading)

** Only for test voltages 500 V_{DC}, 1000 V_{DC} and 2500V_{DC}. If any insulation resistance values (*R_{ISO}(60s) or R_{ISO}(10min)) are overranged the* **PI** factor is not calculated. The result field is blank: PI :_____!

10.3 Continuity

10.3.1 Resistance R LOW, R2, R1+R2

Measuring range according to EN 61557 is 0.16 Ω ÷ 1999 Ω.

Measuring range R (Ω)	Resolution (Ω)	Accuracy
0.00 ÷ 19.99	0.01	±(3 % of reading + 3 digits)
20.0 ÷ 199.9	0.1	±(5 % of reading)
200 ÷ 1999	1	

Measuring range R+, R- (Ω)	Resolution (Ω)	Accuracy
0.0 ÷ 199.9	0.1	±(5 % of reading + 5 digits)
200 ÷ 1999	1	

Open-circuit voltage.....6.5 VDC ÷ 9 VDC
Measuring current.....min. 200 mA into load resistance of 2 Ω
Test lead compensation.....up to 5 Ω
The number of possible tests.....> 2000, with a fully charged battery
Automatic polarity reversal of the test voltage.

10.3.2 Resistance CONTINUITY

Measuring range (Ω)	Resolution (Ω)	Accuracy
0.0 ÷ 19.9	0.1	±(5 % of reading + 3 digits)
20 ÷ 1999	1	

Open-circuit voltage.....6.5 VDC ÷ 9 VDC
Short-circuit current .....max. 8.5 mA
Test lead compensation.....up to 5 Ω

10.3.3 RING Continuity

Measuring range according to EN 61557 is 0.16 Ω ÷ 1999 Ω.

Measuring range R (Ω)	Resolution (Ω)	Accuracy
0.00 ÷ 19.99	0.01	±(3 % of reading + 3 digits)
20.0 ÷ 199.9	0.1	±(5 % of reading)
200 ÷ 1999	1	

Open-circuit voltage.....6.5 VDC ÷ 9 VDC
Measuring current.....min. 200 mA into load resistance of 2 Ω
Test lead compensation.....up to 5 Ω
The number of possible tests .....> 2000, with a fully charged battery

10.4 RCD testing

10.4.1 General data

Nominal residual current (A,AC) .....10 mA, 30 mA, 100 mA, 300 mA, 500 mA, 1000 mA
Nominal residual current accuracy.....-0 / +0.1·IΔ; IΔ = IΔN, 2×IΔN, 5×IΔN
-0.1·IΔ / +0; IΔ = 0.5×IΔN
AS/NZS selected: ± 5 %
Test current shape.....Sine-wave (AC), pulsed (A, F), smooth DC (B, B+)
DC offset for pulsed test current .....6 mA (typical)
RCD type .....(non-delayed), S (time-delayed), PRCD, PRCD-K, PRCD-S
Test current starting polarity ..... 0º or 180º
Voltage range .....93 V ÷ 134 V (45 Hz ÷ 65 Hz)
185 V ÷ 266 V (45 Hz ÷ 65 Hz)

	$I_{\Delta N}$ × 1/2			$I_{\Delta N}$ × 1			$I_{\Delta N}$ × 2			$I_{\Delta N}$ × 5			RCD I_{Δ}		
$I_{\Delta N}$ (mA)	AC	A, F	B, B+	AC	A, F	B, B+	AC	A, F	B, B+	AC	A, F	B, B+	AC	A, F	B, B+
10	5	3.5	5	10	20	20	20	40	40	50	100	100	✓	✓	✓
30	15	10.5	15	30	42	60	60	84	120	150	212	300	✓	✓	✓
100	50	35	50	100	141	200	200	282	400	500	707	1000	✓	✓	✓
300	150	105	150	300	424	600	600	848	n.a.	1500	n.a.	n.a.	✓	✓	✓
500	250	175	250	500	707	1000	1000	1410	n.a.	2500	n.a.	n.a.	✓	✓	✓
1000	500	350	500	1000	1410	n.a.	2000	n.a.	n.a.	n.a.	n.a.	n.a.	✓	✓	n.a.

n.a.....not applicable
AC type.....sine wave test current
A, F types…… .....pulsed current
B, B+ types .....smooth DC current (MI 3102 BT only)

10.4.2 Contact voltage RCD Uc

Measuring range according to EN 61557 is 20.0 V ÷ 31.0V for limit contact voltage 25V
Measuring range according to EN 61557 is 20.0 V ÷ 62.0V for limit contact voltage 50V

Measuring range (V)	Resolution (V)	Accuracy
0.0 ÷ 19.9	0.1	(-0 % / +15 %) of reading ± 10 digits
20.0 ÷ 99.9	0.1	(-0 % / +15 %) of reading

The accuracy is valid if mains voltage is stabile during the measurement and PE terminal is free of interfering voltages.

Test current ..... max. 0.5×$I_{\Delta N}$
Limit contact voltage..... 25 V, 50 V
Specified accuracy is valid for complete operating range.

10.4.3 Trip-out time

Complete measurement range corresponds to EN 61557 requirements.
Maximum measuring times set according to selected reference for RCD testing.

Measuring range (ms)	Resolution (ms)	Accuracy
0.0 ÷ 40.0	0.1	±1 ms
0.0 ÷ max. time *	0.1	±3 ms

* For max. time see normative references in chapter *4.4.5 RCD testing* – this specification applies to max. time >40 ms.

Test current ..... ½×$I_{\Delta N}$, $I_{\Delta N}$, 2×$I_{\Delta N}$, 5×$I_{\Delta N}$
5×$I_{\Delta N}$ is not available for $I_{\Delta N}$=1000 mA (RCD type AC) or $I_{\Delta N} \geq$ 300 mA (RCD types A, F).
2×$I_{\Delta N}$ is not available for $I_{\Delta N}$=1000 mA (RCD types A, F).
Specified accuracy is valid for complete operating range.

10.4.4 Trip-out current

Trip-out current
Complete measurement range corresponds to EN 61557 requirements.

Measuring range I_Δ	Resolution I_Δ	Accuracy
0.2×$I_{\Delta N}$ ÷ 1.1×$I_{\Delta N}$ (AC type)	0.05×$I_{\Delta N}$	±0.1×$I_{\Delta N}$
0.2×$I_{\Delta N}$ ÷ 1.5×$I_{\Delta N}$ (A type, $I_{\Delta N}$ ≥30 mA)	0.05×$I_{\Delta N}$	±0.1×$I_{\Delta N}$
0.2×$I_{\Delta N}$ ÷ 2.2×$I_{\Delta N}$ (A type, $I_{\Delta N}$ <30 mA)	0.05×$I_{\Delta N}$	±0.1×$I_{\Delta N}$
0.2×$I_{\Delta N}$ ÷ 2.2×$I_{\Delta N}$ (B type)	0.05×$I_{\Delta N}$	±0.1×$I_{\Delta N}$

Trip-out time

Measuring range (ms)	Resolution (ms)	Accuracy
0 ÷ 300	1	±3 ms

Contact voltage

Measuring range (V)	Resolution (V)	Accuracy
0.0 ÷ 19.9	0.1	(-0 % / +15 %) of reading ± 10 digits
20.0 ÷ 99.9	0.1	(-0 % / +15 %) of reading

The accuracy is valid if mains voltage is stabile during the measurement and PE terminal is free of interfering voltages.
Trip-out measurement is not available for $I_{\Delta N}$=1000 mA (RCD types B, B+).
Specified accuracy is valid for complete operating range.

10.5 Fault loop impedance and prospective fault current

10.5.1 No disconnecting device or FUSE selected

Fault loop impedance

Measuring range according to EN 61557 is 0.25 Ω ÷ 9.99kΩ.

Measuring range (Ω)	Resolution (Ω)	Accuracy
0.00 ÷ 9.99	0.01	±(5 % of reading + 5 digits)
10.0 ÷ 99.9	0.1	
100 ÷ 999	1	± 10 % of reading
1.00 k ÷ 9.99 k	10	

Prospective fault current (calculated value)

Measuring range (A)	Resolution (A)	Accuracy
0.00 ÷ 9.99	0.01	Consider accuracy of fault loop resistance measurement
10.0 ÷ 99.9	0.1	
100 ÷ 999	1	
1.00 k ÷ 9.99 k	10	
10.0 k ÷ 23.0 k	100	

The accuracy is valid if mains voltage is stabile during the measurement.

Test current (at 230 V)..... 6.5 A (10 ms)
Nominal voltage range..... 93 V ÷ 134 V (45 Hz ÷ 65 Hz)
185 V ÷ 266 V (45 Hz ÷ 65 Hz)

10.5.2 RCD selected

Fault loop impedance

Measuring range according to EN 61557 is 0.46 Ω ÷ 9.99 kΩ.

Measuring range (Ω)	Resolution (Ω)	Accuracy
0.00 ÷ 9.99	0.01	±(5 % of reading + 10 digits)
10.0 ÷ 99.9	0.1	
100 ÷ 999	1	± 10 % of reading
1.00 k ÷ 9.99 k	10	

Accuracy may be impaired in case of heavy noise on mains voltage.

Prospective fault current (calculated value)

Measuring range (A)	Resolution (A)	Accuracy
0.00 ÷ 9.99	0.01	Consider accuracy of fault loop resistance measurement
10.0 ÷ 99.9	0.1	
100 ÷ 999	1	
1.00 k ÷ 9.99 k	10	
10.0 k ÷ 23.0 k	100	

Nominal voltage range..... 93 V ÷ 134 V (45 Hz ÷ 65 Hz)
185 V ÷ 266 V (45 Hz ÷ 65 Hz)

No trip out of RCD.

10.6 Line impedance and prospective short-circuit current / Voltage drop

Line impedance

Measuring range according to EN 61557 is 0.25 Ω ÷ 9.99kΩ.

Measuring range (Ω)	Resolution (Ω)	Accuracy
0.00 ÷ 9.99	0.01	±(5 % of reading + 5 digits)
10.0 ÷ 99.9	0.1	
100 ÷ 999	1	± 10 % of reading
1.00 k ÷ 9.99 k	10	

Prospective short-circuit current (calculated value)

Measuring range (A)	Resolution (A)	Accuracy
0.00 ÷ 0.99	0.01	Consider accuracy of line resistance measurement
1.0 ÷ 99.9	0.1	
100 ÷ 999	1	
1.00 k ÷ 99.99 k	10	
100 k ÷ 199 k	1000	

Test current (at 230 V)..... 6.5 A (10 ms)
Nominal voltage range..... 93 V ÷ 134 V (45 Hz ÷ 65 Hz)
185 V ÷ 266 V (45 Hz ÷ 65 Hz)
321 V ÷ 485 V (45 Hz ÷ 65 Hz)

Voltage drop (calculated value)

Measuring range (%)	Resolution (%)	Accuracy
0.0 ÷ 99.9	0.1	Consider accuracy of line impedance measurement(s)*

Z_{REF} measuring range..... 0.00 Ω ÷ 20.0 Ω

*See chapter *5.8.2 Voltage drop* for more information about calculation of voltage drop result

10.7 PE conductor resistance

10.7.1 No RCD selected

PE conductor resistance

Measuring range (Ω)	Resolution (Ω)	Accuracy
0.00 ÷ 19.99	0.01	±(5 % of reading + 5 digits)
20.0 ÷ 99.9	0.1	
100.0 ÷ 199.9	0,1	± 10 % of reading
200 ÷ 1999	1	

10.7.2 RCD selected

PE conductor resistance

Measuring range (Ω)	Resolution (Ω)	Accuracy
0.00 ÷ 19.99	0.01	±(5 % of reading + 10 digits)
20.0 ÷ 99.9	0.1	
100.0 ÷ 199.9	0,1	± 10 % of reading
200 ÷ 1999	1	

Accuracy may be impaired in case of heavy noise on mains voltage.

Nominal voltage range..... 93 V ÷ 134 V (45 Hz ÷ 65 Hz)
185 V ÷ 266 V (45 Hz ÷ 65 Hz)

No trip out of RCD.

10.8 Resistance to earth

10.8.1 Standard earthing resistance measurement – 3-wire measurement

Measuring range according to EN61557-5 is 2.00 Ω ÷ 1999 Ω.

Measuring range (Ω)	Resolution (Ω)	Accuracy
0.00 ÷ 19.99	0.01	±(5% of reading + 5 digits)
20.0 ÷ 199.9	0.1	
200 ÷ 9999	1	

Max. auxiliary earth electrode resistance R_C ... 100×R_E or 50 kΩ (whichever is lower)
Max. probe resistance R_P ..... 100×R_E or 50 kΩ (whichever is lower)

Additional probe resistance error at R_{Cmax} or $R_{Pmax.}$ ±(10 % of reading + 10 digits)

Additional error at 3 V voltage noise (50 Hz) ... ±(5 % of reading + 10 digits)
Open circuit voltage ..... < 30 VAC
Short circuit current..... < 30 mA
Test voltage frequency ..... 125 Hz
Test voltage shape ..... sine wave
Noise voltage indication threshold ..... 1 V (< 50 Ω, worst case)

Automatic measurement of auxiliary electrode resistance and probe resistance.
Automatic measurement of voltage noise.

10.8.2 Contactless earthing resistance measurement using two current clamps

Measuring range (Ω)	Resolution (Ω)	Accuracy*)
0.00 ÷ 19.99	0.01	±(10% of reading + 10 digits)
20.0 ÷ 30.0	0.1	±(20% of reading)
30.1 ÷ 99.9	0.1	±(30% of reading)

*) Distance between test clamps > 30 cm.

Additional error at 3 V voltage noise (50 Hz) ... ±10 % of reading
Test voltage frequency ..... 125 Hz
Noise current indication ..... yes
Low clamp current indication ..... yes
Additional clamp error has to be considered.

10.9 Specific earth resistance measurements

Measuring range (Ωm)	Resolution (Ωm)	Accuracy
0.0 ÷ 99.9	0.1	See accuracy note
100 ÷ 999	1	
1.00 k ÷ 9.99 k	0.01 k	

10.0 k ÷ 99.9 k	0.1 k	
100 k ÷ 9999 k	1 k	

Measuring range (Ωft)	Resolution (Ωft)	Accuracy
0.0 ÷ 99.9	0.1	See accuracy note
100 ÷ 999	1	
1.00 k ÷ 9.99 k	0.01 k	
10.0 k ÷ 99.9 k	0.1 k	
100 k ÷ 9999 k	1 k	

Principle:
$\rho = 2 \cdot \pi \cdot \text{distance} \cdot Re$,
with Re as measured resistance in 4-wire method.

Accuracy note:

- Accuracy of the specific earth resistance result depends on measured resistance Re and is as follows:

Measuring range (Ω)	Accuracy
1.00 ÷ 1999	±5 % of measured
2000÷ 19.99k	±10 % of measured
>20k	±20 % of measured

Additional error:
See *Earth resistance three-wire method.*

10.10 Voltage, frequency, and phase rotation

10.10.1 Phase rotation

Nominal system voltage range ..... 100 V_{AC} ÷ 550 V_{AC}
Nominal frequency range..... 14 Hz ÷ 500 Hz
Result displayed ..... 1.2.3 or 3.2.1

10.10.2 Voltage

Measuring range (V)	Resolution (V)	Accuracy
0 ÷ 550	1	±(2 % of reading + 2 digits)

Result type..... True r.m.s. (trms)
Nominal frequency range..... 0 Hz, 14 Hz ÷ 500 Hz

10.10.3 Frequency

Measuring range (Hz)	Resolution (Hz)	Accuracy
0.00 ÷ 9.99	0.01	±(0.2 % of reading + 1 digit)
10.0 ÷ 499.9	0.1	

Nominal voltage range..... 10 V ÷ 550 V

10.10.4 Online terminal voltage monitor

Measuring range (V)	Resolution (V)	Accuracy
10 ÷ 550	1	±(2 % of reading + 2 digits)

10.11 TRMS Clamp current

Instrument
Maximum voltage on C1 measuring input..... 3 V
Nominal frequency..... 0 Hz, 40 Hz ÷ 500 Hz

AC current clamp A1018
Range = 20 A

Measuring range (A)	Resolution (A)	Accuracy*
0.0 m ÷ 99.9 m	0.1 m	±(5 % of reading + 5 digits)
100 m ÷ 999 m	1 m	±(3 % of reading + 3 digits)
1.00 ÷ 19.99	0.01	±(3 % of reading)

AC current clamp A1019
Range = 20 A

Measuring range (A)	Resolution (A)	Accuracy*
0.0 m ÷ 99.9 m	0.1 m	indicative
100 m ÷ 999 m	1 m	±(5 % of reading)
1.00 ÷ 19.99	0.01	±(3 % of reading)

AC / DC current clamp A1391
Range = 40 A

Measuring range (A)	Resolution (A)	Accuracy*
0.00 ÷ 1.99	0.01	±(3 % of reading + 3 digits)
2.00 ÷ 19.99	0.01	±(3 % of reading)
20.0 ÷ 39.9	0.1	±(3 % of reading)

Range = 300 A

Measuring range (A)	Resolution (A)	Accuracy*
0.00 ÷ 19.99	0.01	indicative
20.0 ÷ 39.9	0.1	
40.0 ÷ 299.9	0.1	±(3 % of reading + 5 digits)

* Accuracy at operating conditions for instrument and current clamp is given.

10.12 First fault leakage current – ISFL (MI 3102 BT only)

Measuring range (mA)	Resolution (mA)	Accuracy
0.0 ÷ 19.9	0.1	±(5 % of reading + 3 digits)

Measuring resistance.....approx. 390 Ω
Nominal voltage ranges.....93 V ≤ U_{L1-L2} < 134 V
185 V ≤ U_{L1-L2} ≤ 266 V

10.13 Calibrated resistance for IMD testing (MI 3102 BT only)

Threshold indicative insulation resistance

Measuring range (kΩ)	**Resolution (kΩ)**	**Notes**
5 ÷ 640	5	Indicative values Up to 128 steps

Nominal voltage ranges.....93 V ≤ U_{L1-L2} ≤ 134 V
185 V ≤ U_{L1-L2} ≤ 266 V

First fault leakage current at threshold insulation resistance

Measuring range (mA)	**Resolution (mA)**	**Note**
0.0 ÷ 19.9	0.1	calculated value*)

*)See chapter *5.13 Testing of insulation monitoring devices – IMD* for more information about calculation of first fault leakage current at threshold insulation resistance.

10.14 Illumination

10.14.1 Illumination (Luxmeter sensor, type B)

Specified accuracy is valid for complete operating range.

Measuring range (lux)	Resolution (lux)	Accuracy
0.01 ÷ 19.99	0.01	±(5 % of reading + 2 digits)
20.0 ÷ 199.9	0.1	±(5 % of reading)
200 ÷ 1999	1	
2.00 ÷ 19.99 k	10	

Measurement principle .....silicon photodiode with V(λ) filter
Spectral response error .....< 3.8 % according to CIE curve
Cosine error.....< 2.5 % up to an incident angle of ± 85^{O}
Overall accuracy.....matched to DIN 5032 class B standard

10.14.2 Illumination (Luxmeter sensor, type C)

Specified accuracy is valid for complete operating range.

Measuring range (lux)	Resolution (lux)	Accuracy
0.01 ÷ 19.99	0.01	±(10 % of reading + 3 digits)
20.0 ÷ 199.9	0.1	±(10 % of reading)
200 ÷ 1999	1	
2.00 ÷ 19.99 k	10	

Measurement principle .....silicon photodiode
Cosine error.....< 2.5 % up to an incident angle of ± 85^{O}
Overall accuracy.....matched to DIN 5032 class C standard

10.15 General data

Power supply voltage..... 9 V_{DC} (6×1.5 V battery or accu, size AA)
Operation..... typical 20 h
Charger socket input voltage ..... 12 V ± 10 %
Charger socket input current ..... 400 mA max.
Battery charging current ..... 250 mA (internally regulated)
Measuring category ..... 600 V CAT III
300 V CAT IV
Protection classification ..... double insulation
Pollution degree..... 2
Protection degree ..... IP 40

Display..... 128x64 dots matrix display with backlight

Dimensions (w × h × d) ..... 23 cm × 10.3 cm × 11.5 cm
Weight ..... 1.3 kg, without battery cells

Reference conditions
Reference temperature range..... 10 °C ÷ 30 °C
Reference humidity range..... 40 %RH ÷ 70 %RH

Operation conditions
Working temperature range ..... 0 °C ÷ 40 °C
Maximum relative humidity ..... 95 %RH (0 °C ÷ 40 °C), non-condensing

Storage conditions
Temperature range..... -10 °C ÷ +70 °C
Maximum relative humidity ..... 90 %RH (-10 °C ÷ +40 °C)
80 %RH (40 °C ÷ 60 °C)

Communication transfer speed
RS 232..... 57600 baud
USB ..... 256000 baud

Size of memory..... ca 1800 measurements

The error in operating conditions could be at most the error for reference conditions (specified in the manual for each function) +1 % of measured value + 1 digit, unless otherwise specified in the manual for particular function.

Appendix A – Fuse table

A.1 Fuse table – impedances (UK)

Fuse type B

Rated current (A)	Disconnection time [s]		
		0.4	5
	Max. loop impedance (Ω)		
3		12,264	12,264
6		6,136	6,136
10		3,68	3,68
16		2,296	2,296
20		1,84	1,84
25		1,472	1,472
32		1,152	1,152
40		0,92	0,92
50		0,736	0,736
63		0,584	0,584
80		0,456	0,456
100		0,368	0,368
125		0,296	0,296

Fuse type C

Rated current (A)	Disconnection time [s]		
		0.4	5
	Max. loop impedance (Ω)		
6		3,064	3,064
10		1,84	1,84
16		1,152	1,152
20		0,92	0,92
25		0,736	0,736
32		0,576	0,576
40		0,456	0,456
50		0,368	0,368
63		0,288	0,288
80		0,232	0,232
100		0,184	0,184
125		0,144	0,144

Fuse type D

Rated current (A)	Disconnection time [s]		
		0.4	5
	Max. loop impedance (Ω)		
6		1,536	1,536
10		0,92	0,92
16		0,576	0,576
20		0,456	0,456
25		0,368	0,368
32		0,288	0,288
40		0,232	0,232
50		0,184	0,184
63		0,144	0,144
80		0,112	0,112
100		0,088	0,088
125		0,072	0,072

Fuse type BS 88-3 (system C)

Rated current (A)	Disconnection time [s]		
		0.4	5
	Max. loop impedance (Ω)		
5		8,36	12,264
16		1,936	3,288
20		1,632	2,704
32		0,768	1,312
45			0,832
63			0,576
80			0,424
100			0,32

Fuse type BS 88-2 (systems E and G)

Rated current (A)	Disconnection time [s]		
		0.4	5
	Max. loop impedance (Ω)		
6		6,568	10,24
10		3,912	5,752
16		2,048	3,344
20		1,416	2,36
25		1,08	1,84
32		0,832	1,472
40			1,08
50			0,832
63			0,656
80			0,456
100			0,368
125			0,272
160			0,224
200			0,152

Fuse type BS 1362

Rated current (A)	Disconnection time [s]		
		0.4	5
	Max. loop impedance (Ω)		
3		13,12	18,56
13		1,936	3,064

Fuse type BS 3036

Rated current (A)	Disconnection time [s]		
		0.4	5
	Max. loop impedance (Ω)		
5		7,664	14,16
15		2,04	4,28
20		1,416	3,064
30		0,872	2,112
45			1,272
60			0,896
100			0,424

All impedances are scaled with factor 0.8.

Appendix B – Accessories for specific measurements

The table below presents recommended standard and optional accessories required for specific measurement. Please see attached list of standard accessories for your set or contact your distributor for further information.

Function	**Suitable accessories (Optional with ordering code A….)**
Insulation resistance	❑ Test lead, 3 x 1.5 m ❑ Tip commander (A 1401) ❑ 2.5 kV test lead (2 x 1.5 m)*
R LOWΩ resistance Continuity	❑ Test lead, 3 x 1.5 m ❑ Tip commander (A 1401) ❑ Test lead, 4 m (A 1012)
Ring continuity	❑ Test lead, 3 x 1.5 m ❑ Ring adapter (A 1214)
Line impedance Voltage drop Fault loop impedance	❑ Test lead, 3 x 1.5 m ❑ Mains measuring cable ❑ Tip commander (A 1401) ❑ Three-phase adapter with switch (A 1111)
Earth connection resistance	❑ Test lead, 3 x 1.5 m ❑ Mains measuring cable ❑ Tip commander (A 1401)
RCD testing	❑ Test lead, 3 x 1.5 m ❑ Mains measuring cable ❑ Three-phase adapter with switch (A 1111)
Earth resistance - RE	❑ Test lead, 3 x 1.5 m ❑ Earth test set, 3-wire, 20 m (S 2026) ❑ Earth test set, 3-wire, 50 m (S 2027)
Earth resistance - two clamps	❑ Test lead, 3 x 1.5 m ❑ AC current clamp (A 1018) ❑ AC current clamp (A 1019) ❑ AC/ DC current clamp (A 1391)
Specific earth resistance - ρ	❑ ρ Adapter (A 1199)
Phase sequence	❑ Test lead, 3 x 1.5 m ❑ Three-phase adapter (A 1110) ❑ Three-phase adapter with switch (A 1111)
Voltage, frequency	❑ Test lead, 3 x 1.5 m ❑ Mains measuring cable ❑ Tip commander (A 1401)
Current	❑ AC current clamp (A 1018) ❑ AC current clamp (A 1019) ❑ AC/DC current clamp (A 1391)
Sensor	❑ Luxmeter sensor, type B (A 1172) ❑ Luxmeter sensor, type C (A 1173)
Diagnostic test*	❑ Test lead, 3 x 1.5 m ❑ Tip commander (A 1401)

	❑ 2.5 kV test lead (2 x 1.5 m)*
ISFL**	❑ Test lead, 3 x 1.5 m ❑ Mains measuring cable ❑ Tip commander (A 1401)
IMD checker**	❑ Test lead, 3 x 1.5 m ❑ Plug commander (A 1314) ❑ Tip commander (A 1401)
Auto sequences	❑ Test lead, 3 x 1.5 m ❑ Mains measuring cable ❑ Tip commander (A 1401)

* MI 3102H BT only
** MI 3102 BT only

Appendix C – Commander (A 1401)

C.1 ⚠ Warnings related to safety

Measuring category of commander
Tip commander A 1401
(cap off, 18 mm tip).....1000 V CAT II / 600 V CAT II / 300 V CAT II
(cap on, 4 mm tip).....1000 V CAT II / 600 V CAT III / 300 V CAT IV

- Measuring category of commander can be lower than protection category of the instrument.
- If dangerous voltage is detected on the tested PE terminal, immediately stop all measurements, find and remove the fault!
- When replacing battery cells or before opening the battery compartment cover, disconnect the measuring accessory from the instrument and installation.
- Service, repairs or adjustment of instruments and accessories is only allowed to be carried out by a competent authorized personnel!

C.2 Battery

The commader uses two AAA size alkaline or rechargeable Ni-MH battery cells.
Nominal operating time is at least 40 h and is declared for cells with nominal capacity of 850 mAh.

Notes:
- If the commander is not used for a long period of time, remove all batteries from the battery compartment.
- Alkaline or rechargeable Ni-MH batteries (size AA) can be used. Metrel recommends only using rechargeable batteries with a capacity of 800 mAh or above.
- Ensure that the battery cells are inserted correctly otherwise the commander will not operate and the batteries could be discharged.

C.3 Description of commander



Figure C.1: Front side tip commander (A 1401)



Figure C.2: Back side

Legend:

1	TEST	TEST	Starts measurements. Acts also as the PE touching electrode.
2	LED	Left status RGB LED	
3	LED	Right status RGB LED	
4	LEDs	Lamp LEDs (Tip commander)	
5	Function selector	Selects test function.	
6	MEM	Store / recall / clear tests in memory of instrument.	
7	BL	Switches On / Off backlight on instrument	
8	Lamp key	Switches On / Off lamp (Tip commander)	
9	Battery cells	Size AAA, alkaline / rechargeable NiMH	
10	Battery cover	Battery compartment cover	
11	Cap	Removable CAT IV cap (Tip commander)	

C.4 Operation of commander

Both LED yellow	Warning! Dangerous voltage on the commander's PE terminal!
Right LED red	Fail indication
Right LED green	Pass indication
Left LED blinks blue	Commander is monitoring the input voltage
Left LED orange	Voltage between any test terminals is higher than 50 V
Both LEDs blink red	Low battery
Both LEDs red and switch off	Battery voltage too low for operation of commander

PE terminal test procedure

- **Connect** commander to the instrument.

- **Connect** commander to the item to be tested (see figure C.3).
- Touch PE test probe (the **TEST** key) on commander for at least one second.
- If PE terminal is connected to phase voltage both LEDs will light yellow, the warning message on the instrument is displayed, instrument's buzzer is activated, and further measurements are disabled in Zloop and RCD functions.



Figure C.3: Reversed L and PE conductors (application of plug commander)